

PRIMARY CORNER DESCRIPTION #3 Corner of Tract 38

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO resurvey by Fred Mensch, U.S. Cadastral Engineer; under Instructions dated May 25, 1916 & April 16, 1918, - (DCSO records Vol. 10 Page(s) 4342)

Set an iron post, 3 ft. long, 1" dia., 26" in the ground, for cor. No. 3 of Tract 38, with brass cap mark

T26S		TR38
R2W		<u>3</u>
S34		S35
1918		

from which
A cedar, 18" dia., bears N.37°E., 48 lks. Mkd 3 TR 38 BT

Douglas Co. Surveyors Office - Vernon "Ray" Tracy - Jack Heritage - E. West - Aug. 10, 1967 - C.S. File 54/40-41

Found - 1918 GLO Brass Cap, firmly set, properly marked & in good condition.
The BT for this corner was apparently destroyed in recent logging.

New BT - 10" Cedar N.74°E., 95.7 ft. mkd. "3 TR38 CS BT.

Note - The Brass Cap for the Corner of Sections 34 & 35 bears North 12.5 ft., as called for in field notes.

This corner lies on steep east slope, 100 ft. west of temporary logging road.

BLM dependent resurvey by Dale T. Bedell & Bryan S. Seibold, Cadastral Surveyors & Robert H. Browning, Survey Technician, under Group No. 1638, surveyed July 1992/April 1995 - (DCSO records Vol. 51 (Page(s) 19756-7)

Corner No. 3 of Tract 38, perpetuated by Tracy, in 1967, monumented with an iron post, 1" dia., firmly set, projecting 10" above the ground, with brass cap (properly) mkd. from which a bearing tree mkd. by Tracy

A cedar, 18" dia., bears N.74°E., 145 lks., with a healed blaze.

No suitable trees available within limits.