

PRIMARY CORNER DESCRIPTION East 1/4 Cor. Sec. 22 only

Alias	Description
_____	_____
_____	_____
_____	_____
_____	_____

<p>GLO survey by John A. McQuinn under contract #466, dated April 5, 1883 - (DCSO records Vol. 10 page(s) 4199)</p> <p>-----</p> <p>Set hemlock post, 4" sq. 4 ft. long, 24" in ground for ¼ sec. cor. marked ¼ S on W face, from which A hemlock, 10" dia., bears S.80°E., 12 lks., mkd: ¼ S BT. A maple, 12" dia., bears N.70°W., 14 lks., mkd: ¼ S BT.</p>								
<p>GLO survey by Wm. N. Gibb under contract #783, dated Dec. 3, 1908 - (DCSO records Vol. 10 page(s) 4228-9)</p> <p>-----</p> <p>I retrace N bet. secs. 22 & 23 Falls 67 lks. W of ¼ sec. cor., which is a stake greatly decayed, mkd & witnessed as described by the Surveyor General Set granite stone, 6x10x15", 10" in the ground for ¼ sec. cor. marked ¼ on W face.</p>								
<p>GLO resurvey by Fred Mensch, U.S. Cadastral Engineer; under Instructions dated May 25, 1916 & April 16, 1918, Group 56 - (DCSO records Vol. 10 Page(s) 4304)</p> <p>-----</p> <p>Intersect the orig. ¼ sec. cor. established by Deputy McQuinn in 1883 & reestablished by Deputy Gibb in 1909, which is a granite stone, 5x10x6" above ground, firmly set, marked as described by the surveyor general & witnessed by the orig. BTs of McQuinn survey. The BT on the east is now a dead & broken stub. I now perpetuate this cor. as follows: Set an iron post, 3 ft. long, 1" dia., in the ground, 1 lk. W of cor. with brass cap marked</p> <table border="0"><tr><td style="text-align: center;">¼</td><td style="text-align: right;">Note: This ¼ sec. is</td></tr><tr><td style="text-align: center;">S 22 S 23</td><td style="text-align: right;">now intended to</td></tr><tr><td style="text-align: center;">1916</td><td style="text-align: right;">refer to sec. 23</td></tr><tr><td></td><td style="text-align: right;">only</td></tr></table> <p>from which A hemlock, 14" dia., bears S.15°E., 44 lks., mkd: ¼ S23 BT A maple, 18" dia., bears N.89°W., 11 lks., mkd: ¼ S22 BT. Does not establish a 1/4 Cor. for sec. 22 (East)</p>	¼	Note: This ¼ sec. is	S 22 S 23	now intended to	1916	refer to sec. 23		only
¼	Note: This ¼ sec. is							
S 22 S 23	now intended to							
1916	refer to sec. 23							
	only							
<p>David Edwards - For: Roseburg Resources - 2/2004 - M 143-66</p> <p>-----</p> <p>After discussing the situation with local BLM surveyors I set the missing East ¼ Corner at a latitudinal mid-point between the north 1/16 corner & the west ¼ corner for sec. 23 only. Set - 5/8" x 36" steel rebar with 2½" dia., alum. cap. 27" dia. Cedar bears S.60°W., 14.0 ft. Scribed ¼ S22 BT 15" dia. Fir bears N.56°W., 60.2 ft. Scribed ¼ S22 BT 6 ft. steel posts bear South 2 ft. & West 2 ft.</p>								