

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 23 & 26

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by John A. McQuinn, Deputy Surveyor, under contract No. 466, dated April 5, 1883 - (DCSO records Vol. 10 Page(s) 4198)

Set post, 3 ft. long, & 3" sq., 24" in the ground for the 1/4 sec. cor. marked 1/4 S BT, from which:

- A cedar, 8" dia., bears N.10°E., 21 lks., mkd: 1/4 S BT.
- A fir, 6" dia., bears S.20°W., 12 lks., mkd: 1/4 S BT.

GLO resurvey by Fred Mensch, U.S. Cadastral Engineer; under Instructions dated May 25, 1916 & April 16, 1918, - (DCSO records Vol. 10 Page(s) 4292 & 4302)

Page 4292

Retracing the line bet. secs. 23 & 26; at 40.00 chs I make diligent search for a distance of 10 chs or more in all directions, but find no trace of the 1/4 sec. cor.

Page 4302

(Midpoint) Set an iron post, 3 ft. long, 1" dia., 26" in the ground, for 1/4 sec. cor., with brass cap marked:

$$\frac{1}{4} \begin{array}{l} \underline{S\ 23} \\ S\ 26 \\ 1916 \end{array}$$

from which

- A cedar, 16" dia., bears N.23°E., 4 lks., mkd: 1/4 S23 BT.
- A cedar, 24" dia., bears S.25°E., 5 lks., mkd: 1/4 S26 BT.

I destroy the corresponding cor. of the rejected revision survey & marks on BTs.

Douglas Co. Surveyors Office - Vernon "Ray" Tracy - Jack Heritage - E. West - July 1967 - C.S. File 54/40-49

Found - 1916 GLO brass cap, properly marked
Orig. 24" Cedar, now shattered stump, S.25°E., 3.3 ft., no scribe fd.

No trace NE BT both BTs were probably destroyed by logging several years ago.

New BTs- 28" cedar N.23°W., 60.1 ft. mkd: 1/4 S23 CS BT.
39" cedar S.85°E., 116.6 ft. mkd: 1/4 S26 CS BT.

Note - This corner lies on NW slope in NE corner of cut off unit.

FD. & used on BLM dependent resurvey by G. Steven Popken, Cadastral Surveyor, Group No. 871, surveyed June/Sept. 1975 - (DCSO Vol. 46 Page(s) 15722)

continued next page

TOWNSHIP 26 RANGE 02 POINT IDENTIFIER # 540300

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 23 & 26

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

BLM Dependent Resurvey by Kenneth W. Saveland, Cadastral Surveyor, under Group No. 2331, Surveyed April/Oct. 2011 - (DCSO records Vol. 58 Page(s) 22927)

The ¼ sec. cor. of secs. 23 and 26, monumented with an iron post, 1" dia., firmly set, bent W., projecting 17" above ground, with brass cap (properly) mkd. from which the BTs mkd. by the Douglas Co Surveyor's Office in 1967

A cedar, 49" dia., bears S.85°E., 117.5 ft., with a healed blaze.

A cedar, 40" dia., bears N.23°W., 57.8 ft., with no marks visible on open blaze.

Straighten iron post, 36" long, and reset to 30" in ground. Raise a mound of stone, 3 ft. base, to top.