

TOWNSHIP 26 RANGE 02 POINT IDENTIFIER # 600300

PRIMARY CORNER DESCRIPTION Cor. Secs 23, 24, 25, & 26

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GL0 survey by John McQuinn, Deputy Surveyor, under contract No. 466, dated April 5, 1883 - (DCSO recs Vol. 10 Page 4189)

Set chinquapin post, 4 ft. long, 4" sq., 24" in the ground for cor. of secs. 23, 24, 25, & 26, mkd T26S S24 on NE, R2W S25 on SE, S26 on SW & S23 on NW faces with 2 notches on S and 1 notch on E edges, from which

 A fir, 36" dia. bears N.60°E., 42 lks mkd: T26S R2W S24 BT

 A chinquapin, 10" dia., bears S.50°E., 28 lks., mkd: T26S R2W S25 BT.

 A chinquapin, 8" dia., bears S.30°W., 30 lks., mkd: T26S R2W S26 BT.

 A chinquapin, 8" dia., bears N.20°W., 18 lks., mkd: T26S R2W S23 BT.

GL0 resurvey by Fred Mensch, U.S. Cadastral Engineer; under Instructions dated May 25, 1916 & April 16, 1918, - (DCSO records Vol. 10 Page(s) 4291 & 4297-8)

Page 4291

... North, retracing the line bet. secs. 25 & 26; ... at 87.27 chs. fall 20 lks. E of cor. of secs. 23, 24, 25, & 26.

Page 4297-8

Intersect the original cor. of secs. 23, 24, 25 & 26 established by Deputy McQuinn in 1883; the old post has been obliterated by decay, but its position is shown by a ring of stones, evidently originally placed around the post. The cor. is witnessed as described by the surveyor general, except for slight discrepancies in the position of the BTs. I now perpetuate this cor., as follows: at the exact cor. point. Set an iron post, 3 ft. long, 2" dia., 24" in the ground, for cor. of secs. 23, 24, 25 and 26, with brass cap marked:

T26S R2W	
S 23 S 24	
S 26 S 25	
1916	

from which

 A fir, 36" dia., bears N.50°E., 40 lks., mkd: T26S R2W S24 BT. (Orig. BT)

 A chinquapin, 10" dia., bears S.50°E., 22 lks., mkd: T26S R2W S25 BT. (Orig. BT)

 A chinquapin, 10" dia., bears S.30°W., 30 lks., mkd: T26S R2W S26 BT. (Orig. BT)

 A chinquapin, 8" dia., bears N.20°W., 21 lks., mkd: T26S R2W S23 BT. (Orig. BT)

I destroy the corresponding cor. of the rejected revision survey and marks on BTs.

Cont.

TOWNSHIP 26 RANGE 02 POINT IDENTIFIER # 600300

PRIMARY CORNER DESCRIPTION Cor. Secs. 23, 24, 25, & 26

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Douglas Co. Surveyors Office - Vernon "Ray" Tracy - Jack Heritage - E. West - Aug. 23, 1967 - C.S. File 54/40-70

Found - 1916 GLO brass cap, firmly set & properly mkd.
Orig. 36" now 48" Fir, alive, N.50°E., 26.4 ft. show good scar. Rescribed "T26S R2W S24 CS BT" in bark
Orig. 8" now 11" Chinquapin snag, N.20°W., 13.9 ft. shows "6S 23" scribe on open blaze.
Orig. SW BT gone & orig. SE BT burned stub.

New BTs- 18" cedar S.5°E., 91.4 ft. mkd: T26S R2W S25 CS BT.
10" Pine snag, N.56°W. 7.9 ft mkd. T26S R2W S23 CSBT
No trees nor stumps to SW.

Note - Corner lies on east edge of old logging road near landing. Secs. 23, 24, & 26 logged off many years ago.

BLM dependent resurvey by G Steven Popken, Cadastral Surveyor Group No. 871, surveyed June/Sept. 1975 - (DCSO Vol. 46 Page(s) 15719-20)

Beginning at the cor. of secs. 23, 24, 25, & 26, monumented with an iron post, 2" dia., firmly set, projecting 10" above ground, with brass cap (properly) mkd., from which the remains of the orig. BTs.

A fir, 46" dia., bears N.53°E., 40 lks., with scribe marks T26S R2W S24 CS visible on bark. This tree was rescribed by Tracy, in 1967. (Record, N.50°E.)

A chinquapin snag, 10" dia., bears N.14°W., 21 lks., with scribe marks 6 W 23 visible on open blaze. (Record, N.20°W.)

and the remains of BTs mkd. by Tracy

A cedar, 20" dia., bears S.6½°E., 138 lks., with scribe mks T26S R2W S26 CS BT visible on open blaze.

A pine snag, 9" dia., bears N.52½°W., 12 lks., with scribe marks T26S R2W S23 CS BT visible on open blaze.

and a new bearing tree

A fir, 7" dia. bears N.80°W., 96 lks. mkd. T26S R2W S23 BT

BLM Dependent Resurvey by Kenneth W. Saveland, Cadastral Surveyor, under Group No. 2331, Surveyed April/Oct. 2011 - (DCSO records Vol. 58 Page(s) 22923)

The cor. of secs. 23, 24, 25, and 26, monumented with an iron post, 2" dia., firmly set, projecting 8" above ground, with brass cap (properly) mkd.
from which the remains of the original bearing trees

continued next page

TOWNSHIP 26 RANGE 02 POINT IDENTIFIER # 600300

PRIMARY CORNER DESCRIPTION Cor Secs 23, 24, 25, & 26

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

A fir, 50" dia., bears N.53°E., 26.4 ft., with a healed blaze and scribe marks T26S R2W S24 C visible in bark.
A burnt, decayed, chinquapin stump, size indeterminate, bears N.14°W., 13.9 ft., with no marks visible.
and a BT mkd. by the Douglas County Surveyor's Office in 1967
A cedar, 28" dia., bears S.6½°E., 91.1 ft., with a healed double blaze.
and a bearing tree mkd. by Popken
A fir, 19" dia., bears N.83°W., 63.4 ft., with a healed blaze. (Record, N.80°W.)
and a new bearing tree
A fir, 9" dia., bears S.34¼°W., 23.8 ft., mkd. T26S R2W S26 BT.
Corner is located 35 ft. E. of an overgrown logging road, 12 ft. wide, bears N.20°E. and S.20°W.
A search was made for all original line trees bet. secs. 24 and 25 as well as bet. secs. 25 and 26 and none were recovered.

Douglas Co. Surveyors Office - Crew: Stephen Flause & Jeff Lorsung- 7/5/2022 - C.S. File 67/54-9

Found - 1916 2½" brass cap on 1¾" I.D. iron pipe, proj. 10", straighten brass cap to plumb, add rough stone mound.
Burnt-sawn 47"x2½' D.Fir stump, N.53°E., 27.2 ft. (rec 26.4) add 3½" PK nail, top center, orig blaze visible in side stump.
A 21" D.Fir N.83°W., 62.7 ft (rec. 63.4) with healed single blaze, add 3½" PK right side center. 1975
Burnt base 12" D.Fir S.34¼°W., 23.5 ft. (rec. 23.8) add 3½" PK nail, right side center. 2011
Note - Corner is 35' e of gravel logging road, course N.20°E. - S.20°W.
Area burnt 9/2020
See sketch in file.
Lat: 43°17'02.37"N Long: 122°53'37.09"W.