

TOWNSHIP 26 RANGE 02 POINT IDENTIFIER # 640100

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Sec. 36; & 1, T27-2

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by S.C. Flint, Contract #459, dated August 3, 1882
- (DCSO records Vol. 10 Page(s) 4185)

Set Cedar post 3 ft. long, 3" sq., 24" in the ground and mkd.
¼ S on N. and S. faces, from which
A Fir 14" dia., bears S.50°W., 9 lks. dist. mkd. ¼ S BT.
A Cedar 16" dia., bears N.30°W., 35 lks. dist. mkd. ¼ S BT

GLO Survey by Fred Mensch, U.S. Surveyor Under Special
Instructions dated May 25, 1916 - (DCSO records Vol. 10
Page(s) 4288)

Intersect the ¼ sec. cor. established by Deputy Flint in 1882
and reestablished by U.S. Surveyor Collier in 1913, which is
a Cedar post 3" sq., 12" above ground, firmly set, mkd. ¼ S36
on N. and 1 on S. face, from which
A Fir 20" dia., bears S.50°W., 9 lks. dist. mkd. ¼ S BT.
A Cedar 16" dia., bears N.30°W., 35 lks. dist. mkd. ¼ S BT
(Original bearing trees of Flint survey)

(Note: At this point in time (July 27, 1997) in the materials
provided for this project, I cannot find a 1913 Collier
description for this corner. V.Laugen)

Douglas County Surveyors Office - Vernon "Ray" Tracy and crew
Aug. 1967 - C.S. File 54/40-50

Found - Unrecorded 1" Iron pipe, firmly set.
Orig. 16" now 24" Cedar, N.30°W., 23.1 ft., now
turned out stump, previously opened and shows
"S36" scribe.
No trace of other original BT.
DO NOT SET BRASS CAP.
New BTs- 7" W.Fir N.26°W., 18.4 ft. mkd. ¼ S36 CS BT.
7" Hemlock S.77°E., 33.8 ft. mkd. ¼ S1 CS BT.
Corner lies on southerly slope in dense brush.

Fd. BC & 2 BTs by D. Edwards, 3/2008 - M155-16