

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 24 & 25

Alias	Description
_____	_____
_____	_____
_____	_____
_____	_____

GLO survey by John A. McQuinn, Deputy Surveyor, under contract No. 466, dated April 5, 1883 - (DCSO records Vol. 10 Page(s) 4190)

-----

Set post, 3 ft. long, 3" sq., 24" in the ground for ¼ sec. cor. mkd ¼ S on N face, from which

A fir, 36" dia., bears North 16 lks., mkd: ¼ S BT.

A cedar, 12" dia., bears South 7 lks., mkd: ¼ S BT.

GLO resurvey by Fred Mensch, U.S. Cadastral Engineer; under Instructions dated May 25, 1916 & April 16, 1918, - (DCSO records Vol. 10 Page(s) 4291 & 4298-9)

-----

Page 4291  
East, retracing line bet. secs. 24 & 25; at 42.29 chs. the ¼ sec. cor. bears South 97 lks.

Page 4298-9  
Intersect the original ¼ sec. cor., established by Deputy McQuinn in 1883 and not reported found in any subsequent survey. The old post is found, badly decayed, witnessed as described by the surveyor general, except that the S bearing tree is down. I now perpetuate this cor., as follows: at the exact cor. point.

Set an iron post, 3 ft. long, 1" dia., 26" in the ground, for ¼ sec cor. with brass cap mkd:

¼	S 24	
	S 25	
		1916

from which

A fir, 36" dia., bears North 16 lks., mkd: ¼ S24 BT.  
(Orig. BT)

A cedar, 18" dia., bears S.20°E., 48 lks., mkd: ¼ S25 BT.

I destroy the corresponding cor. of the rejected revision survey and marks on BTs

Douglas Co. Surveyors Office - Vernon "Ray" Tracy - Jack Heritage - E. West - Aug. 1967 - C.S. File 54/40-64

-----

Found - 1916 GLO Brass Cap, firmly set & properly marked.  
Orig. 36", now 40" Fir north 10.6 ft., Alive, burned, shows scar, do not open.  
1916 - 18", now 22" Cedar, S.20°E. 31.7 ft., alive, scribe visible on unhealed blaze. This BT. in good condition.

New BT - 10" Cedar N.23°W. 27.9 ft. mkd. ¼ S24 CS BT.

Note - This corner lies on west slope approx. 175 ft. N. of dry ravine & 340 ft. west of top of spur, sloping NW on old E-W cutting line, cut-off to north.

cont.

TOWNSHIP 26 RANGE 02 POINT IDENTIFIER # 640300

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 24 & 25

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

BLM Dependent Resurvey by Kenneth W. Saveland, Cadastral Surveyor, under Group No. 2331, Surveyed April/Oct. 2011 - (DCSO records Vol. 58 Page(s) 22924)

-----

The ¼ sec. cor. of secs. 24 and 25, perpetuated by the Douglas County Surveyor's Office in 1967, monumented with an iron post, 1" dia., firmly set, projecting 8" above ground, with brass cap (properly) mkd.

from which the remains of an original bearing tree

A fir snag, 35" dia., bears North, 10.6 ft., with a healed blaze.

and a bearing tree mkd. by Mensch

A cedar, 23" dia., bears S.20°E., 31.7 ft., with a healed blaze.

and a BT mkd. by the Douglas County Surveyor's Office

A cedar, 25" dia., bears N.24°W., 27.8 ft., with a healed double blaze.

A search was made for all original line trees bet. secs. 24 and 25 and none were recovered.