

TOWNSHIP 26 RANGE 02 POINT IDENTIFIER # 640400

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 13 & 24

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

GLO survey by John A. McQuinn, Deputy Surveyor, under contract No. 466, dated April 5, 1883 - (DCSO records Vol. 10 Page(s) 4192-3)  
-----  
Set cedar post, 3 ft. long, 3" sq., 24" in the ground for 1/4 sec. cor. mkd 1/4 S on N face, from which  
    A cedar, 8" dia., bears N.55°E., 15 lks., mkd: 1/4 S BT.  
    A fir, 48" dia., bears S.35°W., 71 lks., mkd: 1/4 S BT.

GLO resurvey by Fred Mensch, U.S. Cadastral Engineer; under Instructions dated May 25, 1916 & April 16, 1918, - (DCSO records Vol. 10 Page(s) 4292 & 4301)  
-----  
Page 4292  
East, retracing line bet. secs. 13 & 24; at 40.00 chs the 1/4 sec. cor. bears North, 1.08 chs.  
Page 4301  
Intersect the 1/4 sec. cor., established by Deputy McQuinn in 1883 & reestablished by U.S. Surveyor Collier in 1913\*\*, which is a basalt stone, 5x6x6", above ground firmly set, marked 1/4 on N face, from which  
    A cedar, 18" dia., bears N.55°E., 15 lks. Marked 1/4 S13 BT (Orig. BT)  
    A fir, 12" dia., bears S.47°30'W., 26 lks. Marked 1/4 S24 BT  
\*\* I cannot find any record of Collier being at the 1/4 cor. between secs. 13 & 24. He re-ran the east boundary of T26-2 starting at the corner East sec. cor. of secs 13 & 24 and running North, but he did not run interior lines that I could find. JC DCSO 12/5/2006

Douglas Co. Surveyors Office - Milo E. Godfrey, Deputy - Vernon Tracy - Cletis Putnam - Oct. 1961 - C.S. File 52/77-5  
-----  
Found - Rock 5"x6"x12" had been moved out of position, "1/4" chiseled on rock.  
    Cedar tree, now 30" N.55°E., 9.9 ft. uprooted & down, has been opened previously & good scribing "1/4" visible.  
    All trace of orig. Fir to SW gone.  
    Fir stump 18" S.49°W., 17.2 ft. good scribing "S24" visible.  
Set - Brass cap mkd County Surveyors T26S R2WS13  
    set rock alongside BC Office 1961 S24  
New BTs- 11" I.Cedar N.32 1/2°E., 38.3 ft. mkd: 1/4 S13 CS BT.  
    13" D.Fir S.12°W., 50.7 ft. mkd: 1/4 S24 CS BT.

Found ok 7/20/1967 VRT C.S. FILE 54/40-21 CONT.

Alias	Description

Douglas Co. Surveyors Office - Randall Smith - Stephen J. Flause - 12/20/1984 - C.S. File 62/21-10

-----  
Found - Approx. 5x6x12" stone from 1916 resurvey, mkd "41-"  
Stone set on west edge of brass cap.  
A 1961 brass cap on an IP properly mkd., firmly set  
& protruding 12" from ground. 1961  
No evidence of orig. SW fir found.  
Orig. Cedar, 8" now a 30" dead & fallen cedar with  
opened blaze, partial scribing visible. Root hole  
of this tree bears N.55°E., 9.9 ft.  
No evidence of SW BT fd from 1916 resurvey. A  
private rd has been built through this location.  
11" I.Cedar now 20" DBH with a well healed double  
blaze. No scribing visible bears N.32½°E., 38.3  
ft. 1961  
13" now 21" D.Fir with a well healed double blaze.  
No scribing visible, bears S.12°W., 50.7 ft. 1961  
New BT - An 8" DBH D.Fir scribed ¼ S24 CS BT on a double  
blaze bears S.85°W., ~~95.1~~ ft. 45.1' 10/18/2022 JC  
6" DBH I.Cedar scribed ¼ S13 CS BT on a double blaze  
bears N.46½°W., 53.7 ft.  
Monument lies approx. 75 ft. west of boundary road & approx.  
20 ft. north of a private road to the Circle K (K) Ranch.

BLM dependent resurvey by Jeffrey O. Covington, Cadastral  
Surveyor, under Group No. 2923, surveyed July 2018/March  
2020- (DCSO records Vol. 59 Pages 24080-1)

-----  
The ¼ sec. cor. of secs. 13 & 24, reported by Mensch in  
1916-18; perpetuated by Godfrey, in 1961; subsequently  
perpetuated by Monrean, in 1984; monumented with an iron  
post, 1¼" dia., firmly set, projecting 10" above ground, with  
a brass cap (properly) mkd.  
from which the remains of a bearing tree mkd. by Mensch  
A fir stump, size indeterminate, bears S.18¼°W., 32.6 ft.,  
with scribe marks ¼ S24 visible on open blaze facing  
east. Determined to be disturbed and out of position.  
(Record, S.47½°W., 17.2 ft.)  
and the bearing trees mkd. by Godfrey  
A cedar, 29" dia., bears N.30¾°E., 38.0 ft., with a healed  
blaze. A fir, 30" dia., bears S.10½°W., 50.5 ft., with  
a healed blaze.  
and the bearing trees mkd. by Monrean  
A fir, 20" dia., bears S.85°W., 94.7 ft., with a healed  
blaze.  
A cedar, 6" dia., bears N.47¼°W., 53.9 ft., with illegible  
scribe marks visible on partially healed blaze. CONT.

TOWNSHIP 26 RANGE 02 POINT IDENTIFIER # 640400

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 13 & 24

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Corner is located W., 50 ft., of Boundary Road, graveled surface, 14 ft. wide, bears N.20°E. and S.20°W. and located N., 20 ft., of a dirt road, 8 ft. wide, bears S.35°E. and N.35°W.

Douglas Co. Surveyors Office - Crew: Stephen Flause & Jeff Lorsung- 10/10/2022 - C.S. File 67/54-24

-----  
Found - 2½" DCS0 brass cap on 1" Iron pipe. Orig stone on west edge of brass cap.  
Singed 27" I. Cedar N.30½°E., (rec. N.32½°E.) 38.3 ft. add 3½" mag nail right side center.  
Burned-sawn 34"x3' D.Fir stump S.11°W., 50.5 ft. (rec S.12°w., 50.7 ft) add 3½" mag nail top center healed double blaze.  
Burnt-dead 21" D.Fir S.85°W., 45.1 ft fully healed double blaze.  
Burnt-dead 6" I.Cedar N.46½°W., 53.7 ft., blazes burned away inside of tree  
2 Alum. Post 0.3 ft. east and 0.3 ft. south.  
Note - Corner is approx. 75' west of Boundary Road & 20' North of private Drive  
Area burnt 9/2020  
Compass decl. 14½°E.  
Lat: 43°17'58.76"N Long: 122°53'59.75"W