

TOWNSHIP 26 RANGE 03 POINT IDENTIFIER # 100340

PRIMARY CORNER DESCRIPTION ¼ cor. Secs. 19; & 24 T26-4

Alias	Description
_____	_____
Alias	Description
_____	_____
Alias	Description
_____	_____
Alias	Description
_____	_____

Original - Addison R. Flint, Contract #56 dated March, 1855
(DCSO Records, Volume 10 Page 4347-8)

Set ¼ sec. post, from which
A B.Oak 8" dia. bears S.40°E., 44 lks. dist.
A B.Oak 6" dia. bears S.25°W., 35 lks. dist.

J. W. Cole, Deputy - Wit. A.Schloeman; S.C. Bruce; Cecil
Black - April 17, 1916 - Volume 2 Pages 274-7

Set Oak post from which the original bearing trees:
A B.Oak 10" dia. S.40°E., 44 lks.
A B.Oak 14" dia. S.25°W., 35 lks.
New BT -A B.Oak 30" dia. N.30°W., 12 lks.

B.B. Irving , Doug. Co. Surveyor - Wit: N.E. Richardson;
B.A. Lane; Allen Moore - May 24, 1929 - C.S. File 7/54

One orig. BT standing chopped out.
Post set by Cole standing.
Oak BT set by Cole dying.
Blazed and scribed:
16" Fir S.43½°W., 20 lks. ¼S24 CS BT.
Drove 1" x 16" bar alongside Cole's post.

James W. Byron, Dep. Co. Surveyor - Milo Godfrey; S.A. Bilow;
March 19, 1959 - C.S. File 49/48-3

Found - 1¼" Iron bar at corner.
16" now 18" Fir stump, I open & find good scribing
"BT". (Rec. S.43½°W., 13.2 ft.) I find should
be S.53°W., 13.2 ft.
Also find, now 32" Oak snag checks record distance
& Bearing as recorded by Cole.
Set brass cap alongside iron bar & mkd. County Surveyors
Office, 1959 ¼ S24|S19 T26S R4W R3W.
New BTs- 9" R.Fir bears S.63°E., 74.0 ft. scribed ¼ S14 CSBT.
4" R.Fir bears S.50°W., 83.0 ft. scribed ¼ S24 CSBT.

Doug. Co. Surveyors Office - V. Tracy - Dec. 4, 1967 - C.S.
File 54/7-71

Found - 1959 DCSO brass cap and BTs:
9" R.Fir S.63°E., 74.0 ft., alive, healed blaze.
4" R.Fir S.50°W., 83.0 ft. alive, healed blaze.
Set - 6 ft. steel fence post alongside brass cap.

continued next page

TOWNSHIP 26 RANGE 03 POINT IDENTIFIER # 100340

PRIMARY CORNER DESCRIPTION ¼ cor Secs. 19; & 24 T26-4

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Found OK in August 1994 by DeGroot - M120-65
Douglas Co. Surveyors Office - Randall W. Smith, Deputy - Stephen J. Flause - 11/1/2000 - C.S. File 66/18-4 ----- Found - 1959 DCS0 brass cap iron pipe protrudes 12" out of ground. 1" iron bar flush with ground on south edge of BC/IP. 1929 8" B.Oak now root hole with rotted Oak & new small trees growing from old roots bears S.40°E., 29.0 ft. (OBT) 6" B.Oak now root hole with rotted Oak roots, bears S.25°W., 23.1 ft. (OBT) 30" now 30" dia., down & rotted B.Oak, root hole bears N.30°W., 7.9 ft. (1916) 16" now 18" dia., 2½ ft. high D.Fir stump with visible scribing "BT", bears S.67°W., 13.2 ft. (1929 rec. S.43½°W., 13.2', 1959 Rec. S.53°W., 13.2 ft.) 1929 9" now 19" D.Fir with a fully healed double blaze bears S.63°E., 74.0 ft. (1959) 4" now 24" dia., pistol butt D.Fir with a fully healed double blaze. Root crown bears S.48°W., 83.0 ft. (Rec. S.50°W., 83.0 ft.) 1959 New - 12" dia., Chittam* single blazed & scribed "¼ S24 CS BT" bears S.12°W., 35.7 ft. *(Also known as a Cascara Buckthorn) 8" dia., B.Oak double blazed & scribed "¼ S19 CS BT" bears S.36°E., 29.0 ft. Steel fence post form 1967 along East edge of BC/IP. Dec. 17 3/4°E.
Douglas Co. Surveyors Office - John Pike - Stephen J. Flause - 2/6/2008 - C.S. File 67/25-12 ----- FD. BC/IP & all access. OK as per Nov. 2000 DCS0 Renewal.