

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 29 and 30

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

<p>Original - Addison R. Flint, Contract #55 dated March, 1855 (DCSO Records, Volume 10 Page 4367)</p> <p>-----</p> <p>Set ¼ sec. post, from which A B.Oak 9" dia., bears S.25°E., 67 lks. dist. A B.Oak 25" dia., bears S.5°W., 89 lks. dist.</p>
<p>M.B. Germond - Wit: F.S. Blakely; F.B. Lane; W. Smith January 20, 1917 ("Old" corner renewal book, Vol. 1 Pg. 64) (No other source reference found)</p> <p>-----</p> <p>I reestablished corner from the old decayed original BTs and note that bearings and distances do not agree, and set in corner at an interpolated point. Corner is W.Oak post 5x 5 x 30", from which A B.Oak 5" dia., bears S.21¼°E., 4.4 ft. "CS ¼ S BT". A W.Oak 14" dia., bears S.71°W., 35.9 ft. "CS ¼ S BT".</p>
<p>H.L. Eppstein, 1934 - C.S. File 18/52; M 1-71</p> <p>-----</p> <p>BT bearing S.21¼°E., 4.4 ft. gone. I set a 2 x 30" I.P. for corner, and marked: A 10" Fir N.83°E., 24.7 ft. for BT gone.</p>
<p>Doug. County Surveyors Office - Milo E. Godfrey, Deputy; Wm. Stoffel; Mike Stone - Dec. 1963 - C.S. File 53/34-4</p> <p>-----</p> <p>Found - 10" Fir (dead) N.83°E., 24.7 ft., previously opened, good scribing "¼S CS", visible on partially rotted face. (Eppstein's BT) 20" W.Oak S.71°W., 35.9 ft. previously opened. (Germond's BT)</p> <p>Did not find Iron pipe set by Eppstein. Set brass cap at cor. mkd: County Surveyor's Office, 1963 T 26 S R3W ¼ S30 S29</p> <p>New BTs - 10" D.Fir N.37°W., 24.6 ft. mkd. ¼ S30 CS BT. 24" D.Fir N.54°E., 27.0 ft. mkd. ¼ S29 CS BT.</p> <p>Corner is 2.5 ft. south of E &amp; W fence line.</p>
<p>Found OK, L. Dolan, November 1986 - M 103-5 A&amp;B</p>
<p>Douglas Co. Surveyors Office - Randall W. Smith, Deputy - Stephen J. Flause - 12/18/2002 - C.S. File 66/48-20</p> <p>-----</p> <p>Found - 1963 DCSO brass cap/iron pipe protrudes 8" out of ground.</p> <p>continued next page</p>

TOWNSHIP 26 RANGE 03 POINT IDENTIFIER # 200240

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 29 and 30

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

14" now fallen & rotted W.Oak roothole agrees well  
with record S.71°W., 35.9 ft. (1917)  
1934 NE BT now gone.  
10" now 14" dia., D.Fir with a fully healed double  
blaze bears N.37°W., 24.6 ft. (1963)  
24" now 38" dia., D.Fir with a fully healed double  
blaze bears N.54°E., 27.0 ft. (1963)  
New - 7" dia., Maple double blazed & scribed "¼ S29 CS BT"  
bears S.77°E., 25.3 ft.  
4" dia., D.Fir double blazed & scribed "X BT" bears  
S.11½°E., 10.7 ft.  
Corner lies 2½ ft. south of an old down E-W fence  
line.  
Compass decl. 17½°E.

Fd. Ok by Neil Hibbs, 6/2006 - M146-43  
FD. Ok by K. DeGroot, 11/2008 - 2008-0091  
FD BC K. DeGroot, 7/2011 - M162-50