

PRIMARY CORNER DESCRIPTION Sec. Cor. for 17, 18, 19 & 20

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

<p>Original - Addison R. Flint, Contract #55 dated March, 1855 (DCSO Records, Volume 10 Pages 4368)</p> <p>-----</p> <p>Set post cor. to secs. 17, 18, 19 and 20, around which a mound was raised as per instructions. No trees being convenient.</p>
<p>A. Boyer - H. Northcraft; P.C. Armstrong; M.H. McCord Dec. 21, 1949 - C.S. File 40/237B, M 16-76</p> <p>-----</p> <p>Set 1½" x 54" Iron pipe for corner on E & W right of way fence, from which</p> <ul style="list-style-type: none">5/8" Iron rod in the highway R/W line bears N.11°30'E. 404.4 ft. mkd. 894+76.6 (No trees in this quadrant)5/8" Iron rod in the highway R/W line bears N.66°05'W., 360 ft. mkd. 890+00 (No trees in this quadrant)18" W.Oak bears S.5°40'W., 756 ft. mkd. S19 T26S R3W 1581 BT.14" double W.Oak bears S.37°18'E., 755 ft. mkd. S20 T26S R3W 1581 BT.
<p>Found OK, March, 1975, G. Baughman, M 55-64 Found OK, July 1984, Donald Bentz, M 97-75A Found OK in August 1994 by DeGroot - M120-65. Found OK, Jan. 1999 by DeGroot - 1999-0026 Found OK, July 1999 by DeGroot - M 133-7 Found OK, Aug. 2000 by DeGroot - 2001-0008 Found OK, Oct. 2002 by DeGroot - 2002-0058 Found OK, Jan. 2004 by DeGroot - M145-27</p>
<p>Douglas Co. Surveyors Office - John Pike - Stephen J. Flause - 1/8/2008 - C.S. File 67/25-5</p> <p>-----</p> <p>Fd double Oak, S.37°E., 755.0 ft. re-tagged all other accessories gone. Corner falls in fence line of residential area, with direct ties to survey monuments.</p>
<p>Fd. Ok, K. DeGroot, 7/2010 (Filed 10/2012) M164-26</p>
<p> </p>