

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 28 and 33

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

Original - Addison R. Flint, Under Contract #55, dated March 1855 (DCSO records Volume 10 Page 4359)

-----  
Set ¼ sec. post, from which  
    A W.Oak 15" dia., bears S.88°E., 374 lks. dist.  
    A W.Oak 6" dia., bears S.15°W., 231 lks. dist.  
No trees convenient North of line.

Doug. County Surveyors Office - Vernon Tracy; Mike Stone;  
Jack Heritage - March 1966 - C.S. File 54/7-48

-----  
Found - Orig. 6" now 15" W.Oak S.15°W., 152.5 ft. chopped out reverse scribe "4" and partial "S"., face apparently rotted before blaze healed. Ring count reveals 100+.  
No trace of other original BT.  
Set Brass cap at cor. mkd. County Surveyors T26S R3W ¼ S 28 Office, 1966 S 33  
New BTs - 10" D.Fir S.49°W., 80.0 ft. mkd: ¼ S33 CS BT.  
          8" R. Cedar N.33°W., 15.0 ft. mkd. ¼ S28 CS BT.  
Corner lies on SE slope approx 400 ft North of Little River Rd

Douglas Co. Surveyors Office - Randall W. Smith, Deputy -  
Stephen J. Flause - 11/4/1999 - C.S. File 66/13-10

-----  
Found - 2½" brass cap, properly marked, on a 1½" O.D. iron pipe, protrudes 8" above ground. 1966  
          8" now 17" dia., I.Cedar with a fully healed blaze bears N.33°W., 15.0 ft. (Agrees w/rec.) 1966  
          10" now 20" dia., 2 ft. high D.Fir stump with a fully healed blaze, bears S.49°W., 80.0 ft. (agrees w/rec.) 1966  
          6" now 16" dia., dead W.Oak with a previously opened rotted blaze, no scribing visible bears S.15°W., 152.5 ft. (Agrees w/rec.) OBT  
New BTs - 12" dia., D.Fir double blazed & scribed "¼ S28 CS BT" bears N.84°E., 16.9 ft.  
          12" dia., I.Cedar double blazed & scribed "¼ S33 CS BT" bears S.24°E., 39.1 ft.  
An 18"x24"x18" tall protruding boulder we chiseled a 4" "X" on top westerly slopping side, bears S.65½°W., 26.2 ft. **See last Pg for pictures.**

Fd. BC, 4 BTs & rock, 5/2007 - Ron Quimby, M153-2  
FD. OK per 1999 DCSO renewal, 2/19/2008 - John Pike & Stephen Flause, DCSO C.S. 67/25-18

TOWNSHIP 26 RANGE 03 POINT IDENTIFIER # 340200

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 28 & 33

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

