

PRIMARY CORNER DESCRIPTION East 1/16 Cor. Secs. 10 & 15

Alias	Description
_____	_____
_____	_____
_____	_____
_____	_____

A. R. Evans, December 1951 - C.S. File 41/26 & M 13-31 ----- 6" Fir, S.38°W., 3.0 ft. marked E 1/16 Section 15.	
Bureau of Land Management resurvey, by Beck, White & Reynolds Group #'s 242, 491, 527 - Survey June 1962-Aug. 1963 (DCSO Records, Vol. 32 Page 13387) ----- Point for the E 1/16 sec. cor. of secs. 10 and 15. Set an Iron post, 28" long, 2½" dia., 26" in the ground, with brass cap mkd. E 1/16 $\frac{S\ 10}{S\ 15}$ 1962 from which A Fir 6" dia., bears N.51½°E., 17 lks., mkd E 1/16 S10 BT A Fir 9" dia., bears S.82°W., 6 lks., mkd. E 1/16 S15 BT. From this point, an iron pipe ¾" dia., firmly set, protruding 4" above the ground, bears N.51½°W., 0.045 chains dist.	
Found and Used, BLM subdivision of section, by Bishop and Rogers, July/Sept. 1984 (DCSO Records, Vol. 47 Pg 17900)	
Douglas Co. Surveyors Office - Stephen J. Flause - Kody Inda - Dec. 18, 2007 - C.S. File 67/25-3 ----- Found - From the 1951 survey: A ¾" I.D. iron pipe protruding approx. 2" above ground (superceded by the following) From the 1962 BLM survey: A ¾" dia., brass cap (properly mkd) on a 2½" O.D. iron pipe firmly set and protruding approx. 6" above ground. Two orig. BLM BTs found: A fir, 6" dia., now an 8" DBH, 6 ft. tall fir stump with a fully healed single blaze, bears N.51½°E., 11.2 ft. (as per rec) A fir 9" dia., now a 16" DBH D.Fir with a fully healed single blaze bears S.82°W., 4.0 ft. (as per rec.) (Tree was formerly the SW BT for the 1951 monument) The above noted ¾" I.D. IP bears N.51½°W., 3.0 ft. New - An 8" DBH Red Cedar scribed "E 1/16 S10 CS BT" on a double blaze bears N.29°E., 6.8 ft. Note - Monument is on gentle NE slope approx. 350 ft. West of Britt Creek. Compass decl. 16¼°E.	