

PRIMARY CORNER DESCRIPTION N 1/16 Cor. Secs. 34 & 35

Alias	Description
Alias	Description
Alias	Description
Alias	Description

Bureau of Land Management Dependent Resurvey, Survey completed April 23, 1975. Daniel Berry, G.Steven Popken & James Carlson. (DCSO records Vol. 37 Page(s) 15395)

Set- An iron post 28" long, 2½" dia. 22" in the ground, in a mound of stone, 2 ft. base, to top, with brass cap mkd.
N 1/16
S 34 | S 35
1972

New - A Fir 10" dia. bears S.17°E. 19 lks mkd "N 1/16 S35 BT"
A Fir 13" dia. bears S.43°W. 15 lks mkd "N 1/16 S34 BT"

Bureau of Land Management Dependent Resurvey, Survey completed Aug. 4, 1981 by Wayne L. Rogers (DCSO records Vol. 45 Page(s) 17446)

Found- Brass cap properly mkd projecting 6" above ground.
A Fir stump, 10" dia. bears S.20°E., 19 lks with scribe marks N. 1/16 S35 BT visible on open blaze. (rec. S.17°E)
A Fir, 13" dia. bears S.39½°W., 15 lks with healed blaze. (rec. S.43°W.)

New BT- A Cedar, 9" dia. bears S.77½°E., 12½ lks. mkd. "N1/16 S35 BT"

Douglas Co. Surveyors Office - Randall Smith, Stephen Flauser; Sept. 15, 1994 - C.S. File 64/52-17

Found - 3¼" dia. Brass cap on a 2½" O.D. iron pipe protrudes 6" above a 2 ft. dia. mound of stones. (1972 BLM)
10" dia. 3 ft. high D.Fir stump with unhealed blaze, scribing visible "N 1/16 S35 BT" bears S.20°E., 12.5 ft. (agrees with rec.) 1972 BLM
13" dia 50 ft high dead D.Fir snag with fully healed single blaze bears S.39½°W., 9.9 ft. (agrees with rec.) 1972 BLM
9" dia. I.Cedar with a partially healed single blaze, scribing visible "N.1/16 S35 BT" bears S.77½°E., 8.9 ft. 1981 BLM

New - 16" dia. D.Fir double blazed and scribed "N1/16 S35 CS BT" bears N.73°E., 21.5 ft.
8" dia. I.Cedar double blazed and scribed "N1/16 S34 CS BT" bears N.34¼°W., 20.7 ft.
3" dia. I.Cedar double blazed and scribed "X BT" bears S.58°W., 47.3 ft.

continued next page

Alias	Description
Alias	Description
Alias	Description
Alias	Description

Douglas Co. Surveyors Office - Stephen J. Flause - Mike Koch & Dennis Lee, DCPW - July 12, 2012 - C.S. File 67/36-17

Found - 3¼" brass cap (properly mkd) on a 2½" OD IP. Monument is firmly set but soil & rock movement on hillside has caused mon. to lean approx. S.80°W., 0.5 ft from a plumb position.

All measurement to accessories are from monuments plumb position.

A fir 10", now a 10" dia. 2½ ft tall D.Fir stub with an unhealed single blaze showing the scribing "N1/16 S35 BT"; bears S.18°E., 12.8 ft. (rec S.17°E., 12.5 ft is a good face measurement) OBT

A fir 13" dia., now a fallen 14" dia. with a rotted partially healed single blaze (face rotted, no scribing vis.); the center of this tree Roothole bears S.43°W., 9.9 ft. (as per rec.)

A cedar 9" dia., now a double trunk (very small tapered secondary trunk) I.Cedar 12" dia., (main scribed trunk) with a fully healed single blaze; bears S.77½°E., 8.3 ft. (as per record) 1981

A 16" dia., D.Fir, now 16" 8½ ft. tall dead D.Fir stub with a partially healed double blaze, scribed "N 1/16 S35 CS" "BT"; bears N.73°E., 21.5 ft. (as per rec.) 1994

A 3" dia., I.Cedar, now 6" I.Cedar with a fully healed high-low double blaze; bears S.58°W., 47.3 ft. (as per rec.) 1994

An 8" dia., I.Cedar, now 10" I.Cedar with partially healed double blaze with the scribing "N 1/16 S34 CS" "BT" visible; bears N.34¼°W., 20.7 ft. (as per rec.) 1994

Monument is returned to a firmly set plumb condition and now protrudes 8" above ground.

No new accessories, fd accessories are tagged & flagged.

Note - Monument is on steep WNW slope on south side of Rattlesnake Creek. Forested with stunted cedar, pine and fir.

Compass decl. 15½°E.