

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 22 and 23

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Original - Samuel C. Flint, Contract #454, dated June 19, 1882
(DCSO records, Vol. 11 Page 4393)

Set a cherry post, for 1/4 sec. cor. 3 ft. long, 3" sq.,
marked 1/4 S on E and W faces, firmly in the ground, from which
A Fir 8" dia., bears N.87°W., 6 lks. mkd. 1/4 S BT.
A Fir 30" dia., bears N.30°E., 28 lks. mkd 1/4 S BT.

Bureau of Land Management Resurvey by Berry; Popken and
Carlson - Under Group #768 - Survey June 1972-April 1975
(DCSO records, Vol. 37 Page 15400)

Point for the 1/4 sec. cor. of secs. 22 and 23, at
proportionate distance; there is no remaining evidence of the
original cor.

Set a stainless steel post, 28 ins. long, 2 1/2 ins. diam., 22
ins. in the ground, with brass cap mkd. T 26 S R 3 W

1/4
S 22 | S 23
1972

from which

A Cedar 26" dia., bears S.38°E., 43 lks., mkd. 1/4 S23 BT.
A Fir 6" dia., bears S.89°W., 55 lks., mkd. 1/4 S22 BT.

BLM Dependent Resurvey by A Bert Skeesick, Cadastral Surveyor
and Robert H Browning, Survey Tech, Under Group No. 2268,
Surveyed July/Nov. 2009 - DCSO records Vol. 57 Page(s) 22707

The 1/4 sec. cor. of secs. 22 and 23, determined at record
distance from the remains of bearing trees mkd. by Berry,
Popken, and Carlson in 1972-75

A sawed cedar stump, 29" dia., bears S.38°E., 28.4 ft.,
with fragmentary scribe marks visible on a
partially healed blaze.

A fir, 21" dia., bears S.89°W., 36.3 ft., with a healed
blaze.

At the corner point

Set a stainless steel post, 28" long, 2 1/2" dia., 22" in the
ground, with brass cap (properly mkd.

from which

A fir, 6" dia., bears N.63/4°E., 42.4 ft., mkd. 1/4 S23 BT.

Deposit a magnet in a white plastic case at the base of the
stainless steel post.

continued next page

TOWNSHIP 26 RANGE 03 POINT IDENTIFIER # 500340

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 22 & 23

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Douglas Co. Surveyors Office - Crew: Stephen Flause & Jeff Lorsung- 1/24/2022 (Filed 4/12/2022) - C.S. File 67/52-8

Found - BLM brass cap on 2½" I.Pipe, projecting 8" (properly marked)
26"x3½ ft badly burnt Cedar stump S.38°E., 28.4 ft.
No marks. 4" mag nail RT side center.
Broken 20"x6' Fir snag S.88°W., 36.3 ft. healed blaze, 4" mag nail RT side center.
Burnt 8" Fir N.6¾°E., 42.4 ft., partially healed single blaze, illegible scribes. 4" mag nail RT side center.
Note - Area burnt in 9/2020
See sketch in file
Compass decl. 14½°E.
Lat: 43°17'35.94" N Long: 123°01'46.99" W