

PRIMARY CORNER DESCRIPTION 1/4 Sec. Cor. for 14, 15

Alias	Description
Alias	Description
Alias	Description
Alias	Description

Original - Samuel C. Flint, Under Contract #454 dated June 19, 1882 - (DCSO records, Vol. 11 Page 4394)

Set cedar post, 3 ft. long, 3" sq., firmly in the ground, mkd. 1/4 S on E and W faces, from which

A Maple 12" dia., bears N.75°E., 30 lks. dist., mkd. 1/4 S BT.

A Maple, 24" dia., bears S.18°W., 18 lks. dist., mkd. 1/4 S BT.

Bureau of Land Management Resurvey by White, Beck & Reynolds Group #'s 242, 491 and 527, Survey June 1962-Aug. 1963 (DCSO records, Vol. 32 Page 13380)

Point for the 1/4 sec. cor. of secs. 14 and 15, at proportionate distance; there is no remaining evidence of the orig. corner. Set a stainless steel post, 28 ins. long, 2 1/2 ins. diam., 26 ins. in the ground, with brass cap mkd.

T 26 S R 3 W
1/4
S 15 | S 14
1962

from which

A Cedar 25" dia., bears N.20 1/2°E., 60 lks. dist., mkd. 1/4 S14 BT.

A Cedar 20" dia., bears N.75°W., 29 lks. dist., mkd. 1/4 S15 BT.

Bureau of Land Management resurvey by Bishop & Rogers Group #1207, Survey July/Sept. 1984 (DCSO records, Vol. 47 Page 17898)

Found corner monumented with an iron post, 2 1/2" dia., firmly set, projecting 4" above ground, with brass cap missing, from which the remains of bearing trees mkd. by White, Beck, and Reynolds:

A Cedar stump 28" dia., bears N.20 1/2°E., 60 lks. dist., with scribe marks 1/4 S14 BT on partially healed blaze.

A Cedar 23" dia., bears N.75°W., 29 lks. dist., with healed blaze.

At the corner point

(Cont. Next Page)

TOWNSHIP 26 RANGE 03 POINT IDENTIFIER # 500440

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 14 and 15

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Set an iron post, 30" long, 2½" dia., with plastic magnetic breakaway base, 24" in the ground, with brass cap mkd.

T 26 S R 3 W

¼

S 15|S 14

1984

from which a new bearing tree

A Pine 8" dia., bears S.26°E., 41 lks. dist. mkd.

¼ S14 BT.

Deposit 1962 iron post alongside new iron post.