

TOWNSHIP 26 RANGE 03 POINT IDENTIFIER # 540260

PRIMARY CORNER DESCRIPTION CN 1/16 Sec 26

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Bureau of Land Management resurvey, by Popken; Berry and Carlson, Under Group #768, Survey June 1972-April 1975 (DCS0 records, Vol. 37 Page 15406)

Point for the center N 1/16 sec. cor. of sec. 26
Set an iron post, 28" long, 2½" dia., 40" in the ground, with the top 12" below surface of ground, with brass cap mkd:

C
N 1/16 | S 26
C
1972

from which
A fir, 6" dia., bears S.2°E., 49 lks., mkd: CN 1/16 S26 BT
A fir, 6" dia., bears N.12°W., 50 lks. mkd: CN 1/16 S26 BT

BLM Dependent Resurvey by A Bert Skeesick, Cadastral Surveyor and Robert H Browning, Survey Tech, Under Group No. 2268, Surveyed July/Nov. 2009 - DCS0 records Vol. 57 Page(s) 22710

The center N 1/16 sec. cor. of sec. 26, monumented with an iron post, 2½" dia., firmly set, buried 5" below the ground, with brass cap mkd.

C
N 1/16 | S 26
C
1972

from which BTs mkd. by Berry, Popken, and Carlson in 1972-75
A fir, 23" dia., bears S.2°E., 32.3 ft., with a healed blaze.
A fir, 19" dia., bears N.15¼°W., 33.0 ft., with a healed blaze. (Record, N.12°W.)
Corner is located on the N. edge of a dirt road, 12 ft. wide, bears N.30°E. and S.30°W.

Douglas Co. Surveyors Office - Crew: Stephen Flause & Jeff Lorsung- 2/1/2023 - C.S. File 67/55-43

Found - BC position now falls in east should of rebuilt and now graveled road. BC searched for and not found.
Badly burnt, sawn 26"x5' tall D.Fir stump S.2°E., 32.3 ft w/healed blaze add 3½" mag nail top center
Badly burnt, sawn 23"x4½' D.Fir stump N.15¼°W., 33.0', healed blaze add 3½" mag nail top center.

New - 5/8"x30" I.R w/DCS0 plastic cap at referenced cor. position from BTs up 2" in rough mound of stone.

Note - Corner in East shoulder of gravel road.
Compass decl. 14½°E

Lat: 43°16'56.72" N Long: 123°01'11.87"W