

TOWNSHIP 26 RANGE 03 POINT IDENTIFIER # 540300

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 23 and 26

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Original - Samuel C. Flint, Under Contract #454 dated June 19, 1882 (DCSO records, Vol. 10 Page 4388)

Set Cedar post, 3 ft. long 4" sq., for 1/4 sec. cor. marked on N face 1/4 S and on S face, 1/4 S, from which
A Fir 20" dia., bears N.10°E., 37 lks. mkd. 1/4 S BT.
A Fir 30" dia., bears S.45°E., 11 lks. mkd. 1/4 S BT.

Bureau of Land Management resurvey, by Popken; Berry and Carlson, Under Group #768, Survey June 1972-April 1975 (DCSO records, Vol. 37 Page 15399)

Point for the 1/4 sec. cor. of secs. 23 and 26, at proportionate distance; there is no remaining evidence of the original cor.

Set an iron post, 28" long, 2 1/2" dia., 40" in the ground, with the top 12" below surface of ground, with brass cap mkd.

T 26 S R 3 W

1/4 $\frac{S \ 23}{S \ 26}$

1972

from which

A Fir 6" dia., bears N.26°E., 60 lks. mkd. 1/4 S23 BT.

A Fir 20" dia., bears S.22°W., 101 lks. mkd. 1/4 S26 BT.

Found OK, Oct. 1995 by Hoffine - M122-80

BLM Dependent Resurvey by A Bert Skeesick, Cadastral Surveyor and Robert H Browning, Survey Tech, Under Group No. 2268, Surveyed July/Nov. 2009 - DCSO records Vol. 57 Page(s) 22706

The 1/4 sec. cor. of secs. 23 and 26, monumented with an iron post, 2 1/2" dia., firmly set, buried 16 ins. below the ground, with brass cap (properly) mkd.

from which the remains of bearing trees mkd. by Berry, Popken, and Carlson in 1972-75

A fir, 24" dia., bears N.26°E., 39.6 ft., with a healed blaze.

A fir snag, 31" dia., bears S.22°W., 66.7 ft., with a healed blaze.

and a new bearing tree

A cedar, 17" dia., bears S.8°E., 37.7 ft., mkd. 1/4 S26 BT

Corner is located on a shallow SW. slope, 9 ft. E. of a graveled road, 12 ft. wide, bears N.40°W. and S.55°E.

Reported as looked for not found by DCSO, SJ Flause & JA Lorsung, 1/20/2023 C.S. 67/55-27. Destroyed by Road