

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 35 and 36

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Original - L.L. Williams & A.R. Flint, under Contract #151 dated May 23, 1871 (DCSO Records, Volume 10 Page 4375)

Set post for 1/4 sec. cor., from which
A Fir 30" dia., bears S.45°E., 14 lks. dist.
A Fir 15" dia., bears N.75°W., 45 lks. dist.

Bureau of Land Management Dependent Resurvey by Wayne L. Rogers under Group #1058 - Survey June/Aug. 1981 (DCSO Records Volume 45 Page 17435)

1/4 Corner determined at record bearing and distance from the remains of the original bearing trees:
A sawed fir stump 40" dia., bears S.45°E., 14 lks. dist., with axe marks visible on decayed blaze.
A decayed fir stump 24" dia., bears N. 75° W., 45 lks. dist., no marks visible.

At the corner point
Set an alum. post, 28 ins. long, 2 1/2 ins. diam., 22 ins. in the ground, with aluminum cap mkd.

T 26 S R 3 W
1/4
S 35 | S 36
1981

from which new bearing trees
A fir 6" dia., bears S.24 1/2°E., 8 1/2 lks. mkd. 1/4 S36 BT.
A fir 6" dia., bears N.87°W., 17 lks. mkd. 1/4 S35 BT.

Douglas Co. Surveyors Office - John Pike - Stephen J. Flause - 12/5/2007 - C.S. File 67/24-51

Found - 3 1/4" dia., alum cap, properly marked on 2 1/2" O.D. alum post, firmly set, projects 6" above ground.
40" now indeterminate dia., x 2 ft. tall very rotted fir stump, evidence of sawn open blaze, bears S.56°E., 10.4 ft. (Rec. S.45°E., 9.2 ft.) OBT
6" now 12" dia., G.Fir, healed double blaze bears N.87°W., 11.2 ft. (agrees w/rec.) 1981 BT
6" now 9" dia., uprooted windfall D.Fir fully healed double blaze, root hole agrees well w/rec (S.24 1/2°E., 5.6 ft.) 1981 BT

New - Double trunk R.Cedar, southerly trunk is 14" dia. & is scribed "1/4 S36 CS BT" bears N.5 1/2°E., 9.4 ft
11" dia., D.Fir, double blazed & scribed "1/4 S35 CS BT" bears S.26°W., 6.2 ft.

continued next page

TOWNSHIP 26 RANGE 03 POINT IDENTIFIER # 600140

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 35 and 36

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Note - $\frac{3}{4}$ " I.D. iron pipe, fd, projects 18" above ground
bears N.56 $\frac{1}{2}$ °E., 63.7 ft. (NO record)
Corner lies near base of mountain with mature timber
to west & young timber plantation to east.

Douglas Co. Surveyors Office - Crew: Stephen Flause & Jeff
Lorsung- 1/18/2023 - C.S. File 67/55-25

Found - BLM brass cap (properly mkd) on 2 $\frac{1}{2}$ " OD alum. post,
up 4"
Mostly burned away fir stump S.56°E., 10.4 ft.
Burned rotted 12" G.Fir stub, N.87°W., 11.2 ft.
Burned, fallen 14"x4' R.Cedar stump N.5 $\frac{1}{2}$ °E., 9.4 ft.
Burned, dead 14" D.Fir S.26°W., 6.2 ft healed double
blaze, add 3 $\frac{1}{2}$ " mag nail right side center.
3/4" I.D. iron pipe N.56 $\frac{1}{2}$ °E., 63.7 ft (no record)
projects 18".
New - Burnt dead 20" D.Fir N.40°W., 34.2 ft., add 3 $\frac{1}{2}$ " mag
nail right side center. Not blazed or scribed.
Note - Area burnt 9/2020
Compass decl. 14 $\frac{1}{2}$ °E.
ORCS State Plane Coord System South Zone
Cottage Grove - Canyonville
N 157192.659
E 250156.469