

PRIMARY CORNER DESCRIPTION ¼ Cor. for Sec. 36; & 1 of T. 27-3

Alias	Description
Alias	Description
Alias	Description
Alias	Description

Original - Addison R. Flint, Contract #56 dated March, 1855 (DCSO Records, Volume 10 Page 4353)

Set ¼ sec. post, from which
 A Cedar 6" dia., bears South 2 lks. dist.
 A Red Fir 25" dia., bears N.60°W., 2 lks. dist.

Bureau of Land Management remonumentation by Harold Corbin under Group #350, Aug/Nov. 1958 (DCSO records, Volume 29 Page 12442)

Found ¼ corner, determined at record bearing and distance from the two original bearing trees:

 A Red fir 42" dia., bears N.60°W., 2 lks. dist., bark scribed ¼S BT.

 A Cedar 12" diam., bears S., 2 lks. dist., with an old rotted blaze, no scribe marks visible.

At the corner point, set an iron post, 28" long 2½" dia., 23" in the ground, and in a mound of stone, 2½ ft. base, to top, with brass cap mkd.

T 26 S R 3 W

¼ $\frac{S\ 36}{S\ 1}$

T 27 S

1958 from which

 A Hemlock 11" dia., bears N.4°E., 57 lks. dist., mkd.

 ¼ S36 BT.

 A Yew 8" dia., bears S.2°W., 53 lks., mkd. ¼ S1 BT.

Bureau of Land Management survey by Jelley and Rogers, under Group #1093, Survey Sept/Oct. 1982 (DCSO records, Volume 45 Page 17502)

Found corner monumented with an iron post 2½" dia., firmly set, projecting 4" above ground with 1958 brass cap from which the remains of an original bearing tree:

 A Fir snag 42" dia., bears N.60°W., 2 lks. dist., with scribe marks ¼ S BT visible on bark blaze.

and the remains of bearing trees mkd. by Corbin:

 A Hemlock stump 14" dia., bears N.2½°W., 57 lks. dist., with healed blaze. (Record N.4°E.)

 A Hemlock 13" dia., bears S.2°W., 53 lks. dist., with healed blaze. (Record, Yew)

and a new bearing tree:

 A Hemlock 8" dia., bears N.79½°E., 30 lks. dist., mkd. ¼ S36 BT.

continued next page

TOWNSHIP 26 RANGE 03 POINT IDENTIFIER # 640100

PRIMARY CORNER DESCRIPTION ¼ Cor for Sec 36; & 1 of T 27-3

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Douglas Co. Surveyors Office - John Pike - Stephen J. Flause
- 12/5/2007 - C.S. File 67/24-49

Found OK, as per 1982 BLM renewal.

BLM Dependent Resurvey by Kenneth W. Saveland, Cadastral
Surveyor, under Group No. 2500 Admin. file 1104, Surveyed
Aug/Oct. 2011 - (DCSO records BLM Plat 2012-1, T27-3 and Vol.
58 Page(s) 22911-2)

The ¼ sec. cor. of secs. 1 & 36 on the N. bdy. of the Tp,,
monumented with an iron post, 2½" dia., firmly set.
projecting 16" above ground, with brass cap (properly) mkd.
from which the remains of an original bearing tree

A fir snag, 42" dia., bears N.60°W,, 1.3 ft., with scribe
marks 4 S visible on a bark blaze,
and the remains of bearing trees mkd. by Corbin

A hemlock, 23" dia., bears S.2°W., 35.0 ft., with a healed
blaze.

A roothole bears N.2½°W,, 37.6 ft., downhill of which is
a fallen decayed hemlock trunk, size indeterminate,
with no marks visible.

and a bearing tree mkd. by Jelley and Rogers

A hemlock, 16" dia., bears N.82¾°E., 19.8 ft., with a
healed blaze. (Record, N.79½°E.)

Raise a mound of stone, 3 ft. base. to top of iron post.

Corner is located 350 ft. N. of Bond Creek, 4 ft. wide,
course S.65°W., and 30 ft. W. of the same creek, 4 ft. wide,
course S.10°E.

Latitude 43°15'25.18"N. Longitude 123°00'01.26"W.
(NAD 1983 (CORS 96))