

TOWNSHIP 26 RANGE 03 POINT IDENTIFIER # 640300

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 24 and 25

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Original - Samuel C. Flint, Under Contract #454 dated June 19, 1882 (DCSO Records, Vol. 10 Page 4387)

Set cedar post, 3 ft. long, 4" sq., for ¼ sec. cor., firmly in the ground marked on N and S faces ¼ S from which
A Fir 20" dia., bears N.40°E., 23 lks. mkd. ¼ S BT.
A Fir 12" dia., bears S.10°E., 15 lks. mkd. ¼ S BT.

Doug. County Surveyors Office - James W. Byron, Deputy
May 27, 1957 - C.S. File 47/190

Found - Both orig. BTs. The SE BT now 25" dead Fir opened 10 or 20 years ago, old face scribed ¼ SBT. The NE BT shows faint scribe marks (bark scribed), now 36" Fir, checks distance but I find bearing to be N10°E., Rec. N.40°E..
Set brass cap at corner mkd: ¼ S24|S25 T26S R3W County Surveyors Office, 1957.
New BTs - 10" Sugar Pine bears S.78½°E., 31.4 ft. scribed ¼ S25 CS BT.
12" R.Fir bears N.82°E., 3.0 ft. scribed ¼ S24 CS BT.

Weyerhaeuser Timber Company and Youngs Bay Lumber, by Lester E. Calder - Wit: Glen McChesney; Tom Shrum; Don Wright.
April 1960 - C.S. File 51/87-2 (WEYCO 1959 C.S. 115-13)

Found - No trace of GLO record Cedar post.
20" Fir N.40°E., 23 lks., 36" Fir, bark scribed bearing N.90°E.
12" Fir S.10°E., 15 lks., 26" dead Fir scribing visible, bearing and distance good.
County Brass cap Found.
10" S.Pine S.78½°E., 31.4 ft., 10" S.Pine scribed CS S25 BT.
12" R.Fir N.82°E., 3.0 ft., 12" Fir scribed CS S24 BT.
Referenced by McChesney (Plates and nails only)
36" Fir N.07°E., 16.2 ft. (Orig. BT)
12" Fir N.85°E., 2.1 ft. (County BT)

Doug. County Surveyors Office - Karen Reed; P.L. Earle
May 9, 1979 - C.S. File 60/24-32

Found - 1" x 36" I.P. with brass cap protruding 12" above ground.
continued next page

TOWNSHIP 26 RANGE 03 POINT IDENTIFIER # 640300

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 24 and 25

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

20" Fir now 34", bears N.10°E., 19.9 ft. to center
(Rec. N.40°E., 15.2 ft.) Traces of bark
scribing. (Orig.)
Root crown bears S.10°E., 9.9 ft. with a down Fir
alongside, "BT" visible. (Orig.)
10" S.Pine now 14", bears S.78°E., 31.9 ft. with
healed blaze.
12" Fir now 18" bears N.89°E., 3.3 ft. with well
healed blaze.
No new monument set.
New BT - 25" trunk of a triple trunk Cedar bears S.34°W.,
85.7 ft. with scribing "¼ S25 CS BT" in a
double blaze.

Found Brass cap & 4 BTs. - Ronald Geisler, Feb. 1, 1984
C.S. File 58/146-2

Fd. & used on BLM rehabilitation of certain corners, Timothy
J. Moore, Cadastral Surveyor & Robert H. Browning, Surveying
Tech., under Group #2100, & 2300, Surveyed April/May 2004, -
(DCSO records Vol. 55 Page(s) 21499) See 2008 BLM plat.

BLM Dependent Resurvey by A Bert Skeesick, Cadastral Surveyor
and Robert H Browning, Survey Tech, Under Group No. 2268,
Surveyed July/Nov. 2009 - DCSO records Vol. 57 Page(s) 22697

The ¼ sec. cor. of secs. 24 & 25, perpetuated by Reed, in
1979, monumented with an iron post, 1¼" dia., firmly set,
projecting 20" above the ground, w/brass cap (properly) mkd.
from which the remains of the original bearing trees
A fir, 32" dia., bears N.10°E., 16.9 ft., with a healed
blaze. (Record, 15.2 ft.)
A decayed fir stump, size indeterminate, bears S.10°E.,
9.9 ft., with no marks visible.
and the remains of BTs mkd. by James W. Byron, in 1957
A fir, 22" dia., bears N.89°E., 3.3 ft., with a healed
double blaze.
A pine, 19" dia., bears S.78°E., 31.7 ft., with a healed
double blaze.
and a bearing tree mkd. by Reed
A cedar, 21" dia., bears S.33¼°W., 73.7 ft., with a
healed blaze.
Corner is located 60 ft. W. of a dirt road, 10 ft. wide,
bears N.20°W. and S.20°E.
Latitude: 43°17'09.13"N. Longitude: 123°00'00.17"W.
(NAD 1983 (GCRS))

Cont.

TOWNSHIP 26 RANGE 03 POINT IDENTIFIER # 640300

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 24 and 25

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Fd as per 2009 BLM resurvey by D. Edwards, 10/2012 - M164-32

Douglas Co. Surveyors Office - Crew: Stephen Flause & Jeff Lorsung- 8/20/2024 - C.S. File 67/58-52

Found - DCS0 2½" brass cap (properly mkd) bent - re-plumb
add rough mound of stone.
Broken, burned, rotted 28"x1½ ft. Fir stub N.10°E.,
16.9 ft.
Burned, dead 24" Fir N.89°E., 3.3 ft. healed double
blaze.
Burned, dead bark gone 17" pine S.78°E., 31.7 ft.
Burned, dead bark 1/2 gone 19" I.Cedar S.33¼°W.,
73.7 ft. with healed blaze.

Note - Mon on steep NW slope very old regrowth to west,
clear-cut to East.
Area 9/2020
Compass decl. 14¼°E.
Oregon Coordinate Reference System
Cottage Grove - Canyonville Zone
N 165138.247 E 252783.567