

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 1 & 12

Alias	Description
_____	_____
_____	_____
_____	_____
_____	_____

No trace of Brass cap found, due to addition of rip-rap to hold fill of N. Umpqua Hwy.
Set Brass cap at cor. mkd. County Surveyor's T26S R3W
Office 1972 $\frac{1}{4} \frac{S 1}{S 12}$
Note: hole could only be dug 1 ft. deep, built rock mound 5 ft. across & 2 ft. high around pipe. Corner lies 14.0 ft. west of west edge of pavement & across road from Rock Creek Guard Station.

Doug. County Surveyors Office - R.B. Kimberling; M.W. Cline
October 18, 1977 - C.S. File 59/40-49

Found - 1" x 30" I.P. with brass cap, properly mkd., laying 4 ft. west of corner location.
12" now 14" R.Fir bears S.38½°E., 123.1 ft. with well healed double blaze.
36" Cedar bears N.46°E., 80.5 ft. with double blaze scribing "¼ S1 CS BT" in upper blaze.
Set - 1" x 30" I.P. with brass cap set at edge of pavement level mkd: Douglas County Surveyors T 26 S
1977 $\frac{1}{4} \frac{S 1}{S 12}$
R 3 W
No new accessories. Cor. is at west edge of pavement across the road from Rock Creek Guard Station. We set a steel fence post with survey marker sign 1.0 ft. west of brass cap.

Doug. County Surveyors Office - Randall W. Smith; Stephen J. Flause - November 26, 1984 - C.S. File 62/21-13

Found - 1977 DCS0 brass disk on an I.P. flush with ground.
12" now 21" D.Fir with a well healed double blaze bears S.38½°E., 123.1 ft.
36" now 42" Cedar with a partially healed double blaze scribing visible in upper blaze "S BT" bears N.46°E., 80.5 ft.
Steel fence post with sign bears S.67½°W., 1.1 ft.
New BT - 6" Maple, bark scribed "¼ S1 CS BT" which faces S.45°E., bears N.6°W., 23.5 ft.
Cor. is at west edge of pavement (Hwy #138) across hwy. from Rock Creek Guard Station.

continued next page

TOWNSHIP 26 RANGE 03 POINT IDENTIFIER # 640600

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 1 & 12

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Douglas Co. Surveyors Office - John Pike - Stephen J. Flause
- 2/27/2008 - C.S. File 67/25-28

Found OK, 3 live BTs as per rec. Note: 1977 BC/IP now 4"
below ground approx. 1 ft west edge of AC in pullout area.

FD BC, 1' from edge of pavement on hwy, 0.6' below surface,
good condition - by Andrew Ausland, ODOT 8/2011 ST HWY 138-
013 A-C

Douglas Co. Surveyors Office - Crew: Stephen Flause & Jeff
Lorsung- 11/7/2022 - C.S. File 67/55-4

Found - 2½" brass cap on 1" I.D. iron pipe, down 8"
(properly mkd)
Singed-sawn 31"x3 ft D.Fir stump S.38½°E., 122.7 ft.
(rec. 123.1 ft) add 3½" mag nail top center,
possible lower blaze. 1957
60"x2 ft. cedar stump burnt N.46°E., 81.0 ft. (rec.
80.5 ft) 3½" mag nail top center, healed lower
blaze. 1957
Live 20" Maple N.6°W., 23.5 ft. scribe not visible.
1984
New - Galvanized reflector post (no reflector) N.3°W., 9.5
ft.
Note - Corner on west edge of pavement Hwy 138
Area burnt 9/2020
Compass decl. 14½°E.
OCRS Coordinate system
Cottage Grove - Canyonville Zone NAD 88
N 180958.843
E 252465.929