

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

Original Aaron Bowser, Contract dated April, 1856 - Survey approved 1858

-----  
Set post in prairie. Deposited stone 9 x 12. Raised mound with trench as per instructions.

H.L. Eppstein, Co. Surveyor - Wit: J.H. Wolford; W.S. Crear; Guy King - November 6, 1926 - "Old" Cor. Book Page 66 (No other record source found)

-----  
Set stake 4 x 4 x 36" on section line 511.5 ft. East of Section Corner 13, 14, 23 24. Marked:  
14" Red Fir N.48°30'E., 48 ft.

Doug. Co. Surveyors Office - John M. Powell; W. Penley; Jack Heritage - January 15, 1971 - C.S. File 56/1-5

-----  
Found - 14" D.Fir now stump, N.48½°E., 48.0 ft., opened for scribe "T".

This corner lies about 20 ft. west of N-S fence line on west edge of roadway. Eppstein calls for this corner to fall 511.5 ft. east of sec. cor. for 13, 14, 23 & 24. I find 5/8" Iron rod to be 541.0 ft. West of DLC Corner.

Set brass cap at cor. mkd: County Surveyor's T 26 S R 4 W  
Office, 1971 Int. L D L C |

Steel fence post alongside.

New BTs - 36" B.Oak N.1°E., 185.1 ft. scribed "Int. L DLC 43 CS BT".

13" Ash N.35°W., 141.7 ft. scribed "Int. L DLC 43 CS BT".

Doug. Co. Surveyors Office - Gregory Quibell; John Powell May 12, 1983 - C.S. File 62/7-5

-----  
Found - 1971 DCSO brass cap, properly mkd., lying alongside gravel road with pipe badly bent.

14" Fir, now 30" stump with scribed "T" visible in opened blaze.

36" B.Oak, now 38" with healed over blaze.

Set a 2" x 30" Iron pipe with brass cap attached marked:

(Continued Next Page)

PRIMARY CORNER DESCRIPTION Int SW Cor. DLC #43

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

<p>Douglas Co. Surveyor T26S _____ R 4 W 1983 Int. L D.L.C. 43</p> <p>Brass cap protrudes 12" above ground along west edge of one lane gravel road. I place fence post &amp; witness sign one foot west of corner. Bearings &amp; Distances used to set cap are: From 30" Fir stump, S.48½°W., 48.0 ft. From 38" Oak, S.1°W., 185.1 ft. New BT - 24" W.oak scribed "Int L DLC 43 CS BT" in double blaze bears N.18°W., 179.8 ft.</p>
<p>Found OK, K. DeGroot, March 1986 - M 100-41 A&amp;B</p>
<p>Doug. Co. Surveyors Office - Randall Smith; Stephen Flause; September 7, 1989 - C.S. File 64/1-3</p> <p>-----</p> <p>Found - 1983 DCSO brass cap on a 1¼" x 36" long I.Pipe, bent laying on top of ground. 14" now 30" dia. 2 ft. high broken &amp; rotted D.Fir stump, no blazes or scribing seen, bears N.48½°E., 48.0 ft. (agrees w/record) 36" now 36" dia. B.Oak with a fully healed double blaze bears N.1°W., 185.1 ft. (Rec. N.1°E., 185.1 ft.) 24" now 32" dia. W.Oak with a fully healed double blaze bears N.19°W., 179.8 ft. (rec. N.18°W.) 13" Ash now depression with roots, bears N.35°W., 141.7 ft. (agrees w/record) DCSO BC/IP stamped T26S S14 S13 S23 S24 R4W 1981" protrudes 6" above ground in an east-west fence line, bears S.89°W., 537.8 ft. (Rec. 5/8" I.R., west 541.0 ft. in 1971) Section corner bears west, 511.5 ft., 1926 and West in Map # M 6-3)</p> <p>Set - Brass cap monument RESET at the intersection of distances to bearing trees &amp; a record bearing to Fir stump. 1983 DCSO BC/IP is straightened &amp; set 10" below ground. The marks "RESET 1989" are added to brass cap.</p> <p>No new accessories. Corner lies along west edge of gravel road.</p>
<p>Found OK November 1990, D. Bentz, M 112-18 Found OK April 1993, K. DeGroot, M 116-73 Fd as per rec. 11/2020 M Heimburger M177-55</p>