

TOWNSHIP 26 RANGE 04 POINT IDENTIFIER # 100100

PRIMARY CORNER DESCRIPTION Tps Cor (SW Cor Sec 31)

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Original - James E. Freeman Contract #1 dated May 1851
(DCSO records, Volume 11 Page 4424 and 4426)

Set post cor. of T. 26 and 27 S., bet. R. 4 and 5 W., on
slope of hill, from which

- A W.Oak 6" dia. bears S.22°E., 20 lks. dist.
- A W.Oak, 10" dia. bears N.35°W., 92 lks. dist.
- A B.Oak 18" dia. bears N.19½°E., 75 lks. dist.
- A Laurel, 12" dia. bears S.20°W., 78 lks. dist.

Approximately 1901 - Recorded in Vol. 2 Page 266, by (?)

Marked R. Fir tree 15" dia. for Corner, from which:

- R.Fir 16" bears N.87°30'W., 33½ lks. dist.
- R.Fir 10" bears S.30°00'E., 47 lks. (old BT in evid.)
- B.Oak 12" bears N.77°30'E., 82 lks.
- R.Fir 14" bears S.63°00'W., 33 lks.

Wilbur W. Purdy, For Andrew Smith & F. Price - "Tract 1
Plat 2, Roseburg Orchard Co. Plat" Vol. 4 Pg. 63, 6/1912

Set for SW Corner Sec. 31, 2" x 26" Galv. Iron pipe.

Milo E. Godfrey, Deputy; and Crew - Jan. 3, 1964
C.S. File 53/33-1

Found - Corner tree, 24" D.Fir in fence corner. Fences E-W
and N-W.

1 1/8" steel axle N.55°E., 3 ft. from corner tree.
30" Fir stump N.87½°W., 22.1 ft. opened & found good
scribing.

28" Fir stump S.62°W., 21.8 ft. shows good scar.
26" Fir stump S.30°E., 21.0 ft. shows good scar.
No trace found of NE BT.

New BTs - 11" D.Fir N.83°E., 28.8 ft. mkd. T26S R4W S31 CSBT

9" D.Fir N.16°W., 41.3 ft. mkd. T26S R5W S36 CSBT

4" Madrone S.36°E., 51.4 ft. mkd. S6 CSBT.

No trees available SW of corner.

(Cont. Next Page)

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Douglas Co. Surveyors Office - Randall W. Smith, Stephen J. Flause - May 2, 1994 - C.S. File 64/51-6

Found - 15" now 31" dia. D.Fir with 4 healed blazes facing cardinal directions. (1901)
1 1/8" dia. steel axle protrudes 1" above ground bears N.55°E., 3.0 ft. from corner tree. (source unknown)

Accessories Found -

- No original BT's found.
- 16" now 24" dia. 3 ft. high rotting D.Fir stump with illegible scribing visible in a previously opened blaze, bears N.87½°W., 22.1 ft. (agrees w/rec. 1901)
- 14" now 24" dia. 2 ft. high rotting D.Fir stump with a fully healed blaze, bears S.62°W., 21.8 ft. (agrees w/rec. 1901)
- 10" now 24" dia. 2 ft. high rotting D.Fir stump with a fully healed blaze, bears S.27°E., 31.0 ft. (rec. S.30°E., 31.0 ft. 1901)
- S.E. Madrone from 1964 Godfrey renewal now gone.
- 9" now 7" dia. 8 ft. high D.Fir snag with a unhealed blaze and scribing visible "T26S R5W S36 CS BT" bears N.15°W., 41.3 ft. (rec. N.16°W., 41.3 ft.) 1964
- 11" now 17" dia. D.Fir with a fully healed double blaze bears N.83°E., 28.0 ft. (rec. N.83°E., 28.8 ft.) 1964

New Accessories -

- 6" dia. W.Oak, double blazed and scribed "T26S R5W S36 CS BT" bears N.1½°W., 22.3 ft.
- 5" dia. Madrone, bark scribed "T27S R4W S6 CS BT" bears S.45½°E., 21.5 ft.
- 14" dia. Madrone, double blazed and scribed "T27S R5W S1 CS BT" bears S.24°W., 23.7 ft.

Note - Corner lies at the intersection of a 3 way fence corner with fences running easterly, westerly and northerly.