

TOWNSHIP 26 RANGE 04 POINT IDENTIFIER # 300300

PRIMARY CORNER DESCRIPTION Sec. Cor. for 20, 21, 28 & 29

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Original - Addison R. Flint, Contract #56 dated March, 1855
(DCSO Records, Volume 11 Page 4448)

Set post corner of secs. 20, 21, 28 and 29, from which
A B.Oak 8" dia. bears N.67°W., 83 lks. dist.
A B.Oak 26" dia. bears S.69½°W., 252 lks. dist.
A B.Oak 20" dia. bears S.21°E., 238 lks. dist.
A B.Oak 26" dia. bears N.38°E., 74 lks. dist.

N.E. Richardson, Deputy Surveyor - Wit: M.E. Godfrey; L.S.
Kershner - For: Frank Sinnott - July 1947 - C.S. File 69/90
and M 13-45

Set from 1 old BT w/scribe mks N.38°E. 38 lks Scribe destroyed
Set a 1" x 36" Iron pipe with a brass cap mkd: 20, 21, 29, 28
T 26 S, R 4 W, County Surveyors Office.
Pipe set 24" in the ground, from which
W. Oak 12" dia. bears N.12¾°W., 11.3 ft. dist.
W. Oak 14" dia. bears N.74¼°E., 41.3 ft. dist.
W. Oak 12" dia. bears S.31¼°E., 32.8 ft. dist.
W. Oak 12" dia. bears S.50°W., 16.5 ft. dist.
(See State Hwy Series (1938) for prior cor. information.
County Survey records, B-6 and J-8)

Milo Godfrey, Deputy - V. Tracy; M. Stone - Sept. 11, 1962
C.S. File 49/125-105

Found - Iron Pipe with brass cap set by Richardson. Pipe was
bent over & cap mashed into ground.
12" W.Oak S.31¼°E., 32.8 ft. shows 2 good axe scars.
Did not cut open.
28" W.Oak N.37½°E., 49.5 ft. (Orig. BT) shows faint
traces of scribing still visible on badly
rotted old face.
Other 3 BTs mkd. in 1947 have all been bulldozed
out, but stump holes & pieces of oak roots
remain.
Straighten & reset cap in its orig. position. Drive steel
fence post alongside.
New BTs - 11" W.Oak N.18°W., 42.9 ft. mkd: T26S R4W S20 CS BT.
7" W.Oak N.55°E., 46.4 ft. mkd: T26S R4W S21 CS BT.
20" D.Fir S.10°W., 70.5 ft. mkd: T26S R4W S29 CS BT.
Corner lies 25 ft. south of an E-W fence line.

Fd. Ok by Neil Hibbs Feb. 2005 - 2005-0047 A&B