

TOWNSHIP 26 RANGE 05 POINT IDENTIFIER # 041030

PRIMARY CORNER DESCRIPTION S.W. Cor. Dixon DLC #41

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Original - Addison R. Flint, Contract #28 Dated April, 1854

Set post, from which

A B.Oak 20" dia. bears N.46°W., 20 lks.

A B.Oak 8" dia. bears N.87°E., 22 lks.

G.G. Stewart, DCS - Tom Dixon; Claude Crocker; J.H. Short
September 24, 1922 - C.S. File 1/56

I reset from old BTs standing but rotten.

Set - ¾" galv. Iron pipe & mkd. the following trees

B.Oak 20" dia. bears S.41½°E., 5.2 ft.

B.Oak 8" dia. bears N.41½°E., 48.4 ft.

Milo E. Godfrey, Deputy; Wm. Stoffel; M. Stone; M. Darby
April, 1964 - C.S. File 49/125-75

Found - ¾" I.P. at corner.

20" B.Oak S.41½°E., 5.2 ft. now dead & down.

Now 12" B.Oak N.41½°E., 48.3 ft. shows good scar.

Didn't open.

New BT - 20" B.Oak S.61°E., 39.7 ft. mkd. S W DLC 41 CSBT.

Douglas Co. Surveyors Office - Randall Smith & Stephen Flauser
- Oct. 29, 1997 - C.S. 64/78-20

Mon. Fd.- 3/4" O.D. iron pipe protrudes 10" above ground
1922.

Bt's Fd.- No evidence of OBT's found

8" now 15" dia. B.Oak, with a fully healed double
blaze, bears N.41½°E., 48.4' (agrees with
rec.) 1922.

20" B.Oak now rotted oak remains near rec.

"S.41½°E., 5.2' 1922.

20" now 21" dia. B.Oak, with a fully healed double
blaze, bears S.61°E., 39.7' (agrees with
rec.) 1964.

Mon. Set- I.P. drive down, now protrudes 4" above ground.

New Accessories -

12" dia. Madrone bark scribed "SW DLC 41 CS BT",
bears N.84°E., 23.5'.

8" dia. Madrone bark scribed "SW DLC 41 CS BT",
bears N.1½°E., 21.1'.