

TOWNSHIP 26 RANGE 05 POINT IDENTIFIER # 042010

PRIMARY CORNER DESCRIPTION N.E. Cor. Hill DLC #42

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Original - Addison R. Flint, Contract #28 dated April, 1854

Set post from which
 A B.Oak 12" dia. bears S.68°W., 208 lks.
 Raised mound with trench as per instructions

O.F. Theil, County Surveyors Records - For W.B. Lamb
Nov. 9, 1899 - Volume 2 Page 85

Set a stone and mound of stone, from which a B.Oak, 16" dia.
bears N.59¼°W., 2.21 chains.

(Note: Source of following paragraph could not be found)
Original Bt had feel down, but we found the BT on it, also
verified by measure South 17.36 chains to interior corner.
All the original BTs have been cut down, marks were found on
three of the remaining stumps, all agreeing in direction and
distance with the field notes. Present, Lee Barker and John
Fegles, March 20, 1900.

Douglas Co. Surveyors Office - Milo Godfrey - Mar. 1964 -
C.S. File 49/125-61

Fd. 3-way fence cor. at approx. location - Fences North,
South & West from cor - 1899 renewal called for mound of
stones at cor. - stones scattered 8' to 10' in all directions
from fence corner. Can not tell where mound was - no trace
found of either orig. BT or 1899 renewal BT. Fence corner
probably close to DLC cor. DID NOT RENEW.