

TOWNSHIP 26 RANGE 05 POINT IDENTIFIER # 100540

PRIMARY CORNER DESCRIPTION 1/4 Sec. Cor. for 7; & 12 of T26-6

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Original - Elder & Gile, Contract #31 dated April, 1853

Set 1/4 sec. post, from which
 A W.Oak 24" dia. bears N.73 1/2°W., 50 lks.
 A W.Oak 10" dia. bears S.13°E., 14 lks.

Ben B. Irving, Deputy Co. Surveyor - N.R. Richardson; E. Hohinger; Al Smith - March 18, 1929 - C.S. File 22/40

Position identified from one OBT scribe marks nearly rotted off. Drove 2" x 36" Iron pipe & mkd. the following trees:
 Fir 14" dia. bears S.42°W., 84 lks. scribed 1/4 S12 CSBT.
 Fir 10" dia. bears N.31 1/2°E., 36 lks. scribed 1/4 S7 CSBT.

James W. Byron, Deputy Co. Surveyor - For: McKay Milo Godfrey; S. Bilow - May 5, 1959 - C.S. File 49/152

Found - 2" I.P. at corner & both BTs by B.B.I.
 14" now 16" R.Fir S.42°W., 55.4 ft. shows good scar. I do not open.
 10" now 12" stump Fir, shows good scribing N.31 1/2°E., record 23.8 ft. I find to be 47.0 ft.
New BT - 5" R.Fir bears N.32°E., 29.0 ft. scribed 1/4 S7 CSBT.

Mark Smalley, July 1995, M 119-67 - for: Roseburg Resources

Found - 2" Iron pipe in fence corner
BT's FD.- 18" fir, S.42°W., 55.4' healed
 22" fir, N.32°E., 29' healed
 12" fir stump, N.31 1/2°E., 47', rotten
New BT's- 13" fir, S.53°E., 12.7', "1/4 S BT"
 10" fir, N.30°W., 15', "1/4 S BT"

Found OK by D. Edwards, Feb. 1999 - M131-16
Fd. BC by M. Schulze, 11/2012 - M164-47