

PRIMARY CORNER DESCRIPTION Tps. Cor. NW Cor. Section 6

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Original - Elder & Gile, Contract #31 dated April, 1853

Set post cor. to Tps. 25 & 26, South between Ranges
5 & 6 West.

Drove charred stake & raised mound with trench and
pits as per instructions.

Milton L. Baldy - For Don Calpin & O.C. Seiter - "Oregon Pear
Co. Plat A" (now vacated) Volume 3 Page 22 - Jan. 1911

Set Galv. I.P. 2" x 36", driven 6" below the surface at the NW
corner Section 6.

James W. Byron, Deputy, For: Ed Russell - April 1955
C.S. File 47/12

Found - 1½" Iron pipe at fence intersection. Use 1½" I.P.
for section corner. (no record)
All original bearing trees gone. (?)

Blazed and scribed:

10" R.Fir N.17°E., 146.0 ft. S31 T26S R5W CS BT.

16" R.Fir (stool of) 600.0 ft. S.84°E., S6 T26S R5W
CS BT.

No other trees near.

Bureau of Land Management - A. White; D. Beck, Cadastral
Surveyors - May 3-24, 1963 - Vol. 32 Page 13361

Corner determined at the intersection of old wire fences
which extend N. and W. at the SE corner of an old orchard,
from which bearing trees mkd. by James Byron in 1955,

A Fir, 18" dia. bears N.20°E., 224 lks. dist. mkd
with a healed blaze, facing the corner.

A fork of a Fir, 25" dia. bears S.85°E., 910 lks.
dist. mkd. with a healed blaze, facing the cor.

At the corner point:

Set - An iron post 28" long 2½" dia. 24" in the ground,
with brass cap marked:

(cont. next page

TOWNSHIP 26 RANGE 05 POINT IDENTIFIER # 100700

PRIMARY CORNER DESCRIPTION NW Township Cor (NW Cor Sec 6)

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

T 25 S
R 6 W R 5 W
S 36 | S 31
S 1 | S 6
T 26 S
1963

No suitable trees available in Secs. 1 and 36 within limits.

Found OK, D. Bentz, Nov. 1986, M 103-30 - Also on M 106-4
Fd. OK, M. Smalley, July 1995, M 119-67

Douglas Co. Surveyors Office - Randall W. Smith - Stephen J. Flause - 2/11/98 - C.S. File 64/79-26

Found - 3½" dia., brass cap on a 2½" O.D. iron pipe,
protrudes 5" above ground. 1963 BLM
10" now 41" dia., D.Fir with fully healed blazes,
bears N.18½°E., 146.0 ft. (1955 rec. N.17°E.,
146.0 ft.) 1955 DCSO
16" now 30" dia., triple trunked down D.Fir with a
fully healed blaze root hole near. (Rec.
S.84°E., 600.0 ft) 1955 DCSO

New BTs- 30" dia., D.Fir, bark scribed "T25S R6W S36 CS BT"
bears N.13°W., 427.0 ft.
30" dia., D.Fir, bark scribed "T25S R6W S36 CS BT"
bears N.60°E., 324.0 ft.

Note - Corner lies at the intersection of fences running
East, West, & North. No trees south of line.
See sketch in file.

DCSO-GIS Corner visitation - 7/7/2004 - Typed: 01/25/2011 -
C.S. File 67/33-1

Monument - BC/IP 1.25"
Comment - ok

Fd. BC by M. Schulze, 11/2012 - M164-47