

TOWNSHIP 26 RANGE 05 POINT IDENTIFIER # 240600

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 5 and 8

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

<p>Original - Elder &amp; Gile, Contract #31 dated April, 1853 ----- Set ¼ Sec. post, from which     A Y.Oak 20" dia. bears N.17°E., 198 lks.     A Y.Oak 18" dia. bears S.57°E., 26 lks.</p>
<p>Milo E. Godfrey, Deputy Co. Surveyor - Wm. Stoffel; Mike Stone; Mike Darby - March 1964 - C.S. File 49/125-51 ----- Found - Charred Oak snag S.57°E., 17.2 ft. cut open and find good scribing.           Stump hole N.17°E., 130.7 ft. Top of Oak tree lying downhill from stump hole. Trunk of tree completely burned away. Set - Brass cap at cor. mkd. County Surveyors Office 1964           T26S R5W ¼ S5 S 8 New BTs - 24" D.Fir N.1½°E., 60.7 ft. mkd. ¼ S5 CS BT.           9" D.Fir S.55°W., 78.2 ft. mkd. ¼ S8 CS BT. Fence corner, fences W. and N. bears N.68°W., 12.0 ft.</p>
<p>Fd. BC by M. Schulze, 11/2012 - M164-47</p>
<p>Carl Sweeden - For: Tim Clark - Sept. 2016 - M172-33 A&amp;B ----- Found - 2½" 1964 DCS0 brass cap up 0.50' &amp; 1/2" I.Pipe along side up 30" w/coupler at top, fence cor. N.51°W., 7.40'           24" now 37" D.Fir BT, N.1½°E., 60.7' scar vis. W/rotting face, no tag           Very rotten D.Fir stump, S.55°W., 78.2'</p>
<p> </p>