

TOWNSHIP 26 RANGE 05 POINT IDENTIFIER # 600258

PRIMARY CORNER DESCRIPTION MC Left bank Umpq. R. Secs 26 and 25

Alias 856090 Description M.C.
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Original - Elder & Gile, Contract #31 dated April, 1853

Intersect left bank of North Umpqua River. Set meander post, from which:

A W.Oak 10" dia. bears S.28°W., 50 lks.

A W.Oak 8" dia. bears S.18°E., 35 lks.

Course of River S.70°W. Bank 20 feet high.

James W. Byron, for Kohlhagen - January 9, 1956
C.S. File 47/60

Found - ¾" I.P. at corner, checks for bearing & distances to original BT, now 10" W.Oak S.28°W., 33 ft. on old weathered face found scribed T & parts of other scribe marks. I open blaze at base, center rotted but find raised BT on chip cut out. SE BT gone.

Scribed: 10" W.Oak S.5°E., 51.5 ft. M.C. S25 CS BT.

10" W.Oak S.32½°W., 45.5 ft. M.C. S26 CS BT.

Set brass cap at corner mkd. MC. S26|S25 T26S R5W County Surveyor's Office, 1956.

Milo E. Godfrey, Deputy Co. Surveyor - Wm. Stoffel; Mike Stone; Mike Darby - March, 1964 - C.S. File 49/125-64

Found - Brass cap set in 1956 - Also ¾" Pipe.
10" W.Oak S.32½°W., 45.5 ft. alive & in good condition.

10" W.Oak S.5°E., 51.5 ft. Top broken out, may not last long.

10" W.Oak S.28°W., 33 ft. is in very poor condition.

New BT - 20" D.Fir S.44°W., 41.7 ft. mkd. M.C. S26 CS BT"

No trees available to East of line.

Douglas Co. Surveyors Office - Randall W. Smith, Deputy - Stephen J. Flause - 5/18/94 - C.S. File 64/51-8

Found - 2½" dia., brass cap on a 1½" O.D. iron pipe protrudes 19" above ground. Top is bent 16" north of plumb (1956)

- ¾" I.D. iron pipe is found along east edge of BC/IP protruding 4" above ground. Top of ¾" I.P. leans 4" north of plumb (source unknown).

- 1956 BC/IP & ¾" I.P. left as found. Bank is steep & any disturbance to area may break off bank. See C.S. File for profile of bank.

(Cont. Next Page)

TOWNSHIP 26 RANGE 05 POINT IDENTIFIER # 600258

PRIMARY CORNER DESCRIPTION MC Left bank Umpq. R. Secs 26 and 25

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Set - 10" now 10" dia., dead, 20' high, W.Oak snag with previously opened rotted blazes, bears S.26°W., 33.0' (Rec. S.28°W., 33.0') 0BT
- 10" now 9" dia., dead, 20' high, W.Oak snag with a partially healed double blaze, bears S.29½°W., 41.6' (Rec. S.32½°W., 45.5') 1956
- 10" now 10" dia., W.Oak with a fully healed double blaze, bears S.7°E., 45.3' (Rec. S.5°E., 51.5') 1956
- 20" now 24" dia., D.Fir, with a fully healed double blaze, bears S.44°W., 41.7' (Agrees with rec.) 1964
- A 2 3/8" brass cap on a 1 3/8" O.D. by 32" long iron pipe is set at top of River Bank, protrudes 4" above ground. Stamped: DOUGLAS COUNTY SURVEYORS
T26S
B.0.1 R
M.C. BEARS 5
N10°W 65.6 W
FT
1994
OFFICE
bears, S.10°E., 65.6 ft. from M.C. BC/IP. B.0.1 is 4½' West of a South running fence.
Note - 6" W.Oak double blazed and scribed "MC S25 CS BT", bears S.53°E., 27.2'.
- See sketch in C.S. File.
- Corner lies on a steep northerly facing river bank 15' West of a South running fence line.