

PRIMARY CORNER DESCRIPTION WSW Cor. Hannan DLC #42

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Original - Addison R. Flint, Contract #28 dated April, 1854

Set post, from which

A B.Oak 10" dia. bears S.19°E., 29 lks. (129 lks. ?)

Oak 23" dia. bears N.26°W., 87 lks.

J.W. Cole, Deputy - May 1921 N 1-69 & F.B. 51 Pg. 17

I renewed this corner from what I believed to be a stump of the orig. BT which is a stump of a B.Oak 28" dia. Ran S.26°E., 57.2 ft. from stump & set hub from which a B.Oak 18" dia. bearing scars, bears S.19°E., 129 lks. instead of 29 lks. as per field notes. A W.Oak 20" dia. bearing two scars, top one rotted out. Bottom scar bears scribe marks B.T. when I chopped it open. Tree bears N.59°30'E., 36.8 ft. Marked new trees as follows:

A B.Oak 30" dia. bears N.54°20'E., 120 ft.

A B.Oak 20" dia. bears S.32°30'E., 90.5 ft.

James W. Byron, Deputy Co. Surveyor - March 2-16, 1956
C.S. file 47/67

Found - 30" B.O.(now dead) N.54°20'E., 120 ft. scribing visible. This tree mkd. by Cole in 1921.

Cole's SW BT gone.

orig. BT, 20" W.O. N.59°30'E., 36.8 ft. This tree down, face rotted.

Also find 1½" I.P. laying on ground 7 rust marks 3" under surface & checks above BTs for brg.& distance

Set - I.P. with brass cap mkd. W S W cor C1 42 T26S R6W Douglas County Surveyor's Office 1956. Reset Cole's 1½" I.P. at side of brass cap.

New BTs - 12" W.O. North 2.0 ft. mkd. WSW C142 CS BT.

16" B.O. S.12°W., 19.0 ft. mkd. W S W C1 42 CS BT.

Found OK June 1964, M.E.G. CS 52/87-45

Douglas County Surveyors Office - Randall Smith & Stephen Flause - April 21, 1997 - C.S. 64/74-20

CONDITION REPORT ONLY

Mon. Fd.- 2½" dia. Brass cap on a 1½" O.D. iron pipe protrudes 5" above ground. 1956

(Cont. Next Page)

TOWNSHIP 26 RANGE 06 POINT IDENTIFIER # 042030

PRIMARY CORNER DESCRIPTION WSW Cor. Hannan DLC #42

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Accessories Fd.-
23" Oak now large root hole rec. brg. "N26°W.,
57.4'" OBT.
30" B.Oak now 36" dia. 2' high badly rotted Oak
stump rec. Brg. "N54°20'E., 120'. 1921
20" now 21" dia. B.Oak, with healed blazes, bears
S.32½°E., 90.5' (agrees with rec.) 1921.
12" now 16" dia. W.Oak, with a fully healed double
blazes, bears North 2' (agrees with rec.) 1956
16" now 23" dia. B.Oak, with a fully healed double
blaze, bears S.12°W., 19' (agrees with rec.)
1956
Corner lies 10' east of a N-S Fence line.

Fd. OK by M. Heimburger, Aug. 2003 - M142-77
Fd. Ok by K. DeGroot - 12/2005 - M149-12
Fd. Ok by C. Sweeden, 9/2007 - M154-31
Fd. Ok by C. Sweeden, 6/2010 - M160-74