

TOWNSHIP 26 RANGE 06 POINT IDENTIFIER # 061050

PRIMARY CORNER DESCRIPTION SW Cor. Raynor DLC #61

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Original - Addison R. Flint, Contract #28 dated April, 1854

Set post, from which

A W.Oak 18" dia. bears N.88°E., 5 lks.

Raised mound with trench as per instructions.

J.W. Cole, Deputy - April 20, 1921 - F.B. 50 Pg. 53

I renewed this corner from the original bearing tree which was alive & standing & which I chopped open & found the scribe marks. I set an Oak post for cor. & marked new trees as follows:

A B.Oak 30" dia. S.16°15'W., 162.5 ft.

A W.Oak 30" dia. N.19°W., 157.1 ft.

A Rock, 8 x 10 x 12" mkd. Cl. 61 bears N.88°E., 2 ft.

Also an iron pipe set by John Watters, Feb. 1924.

James W. Byron, Deputy - D.McFarland; J.Powell; For: Doug. Co. Parks Dept. - Oct. 26, 1961 - C.S. File 52/95 & M 21-60.

Found - Now 34", dead, W.Oak N.17°W., not N.19°W., 157.1 ft.
Also find 1" I.R. with small flange on top & under surface 6".

Set - We open NW BT & ind scribe marks. SW BT not found.
Brass cap alongside I.R. & mark: SW DLC 61 T26S R6W
County Surveyors Office, 1961.

New BTs - 24" B.Oak bears S.74°E., 37.5 ft. scribed SW CL 61
CS BT.

17" R.Fir bears N.86°W., 46.1 ft. scribed SW CL 61
CS BT.

Corner is in Channel of Creek.

Found OK, December, 1990 - M 111-22

Found Brass cap, no accessories found, Oct. 1993 by G. Baughman M117-70.

Douglas Co. Surveyor - Randall Smith & Stephen Flauser - Nov. 1, 1993 - C.S. 64/47-13

Monuments Fd.:

2½" dia., DCS0 Brass cap on a 1¼" O.D. I.P. protruding 7" above ground. (1961)

(Cont. Next Page)

TOWNSHIP 26 RANGE 06 POINT IDENTIFIER # 061050

PRIMARY CORNER DESCRIPTION SW cor. Raynor DLC #61

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

County Surveyors Office
T 26 S R 6 W
|
S.W.
|
D.L.C. 61
1961

Accessories Fd.

Remains of a rotted oak fd. near record Brg. & Dist. of orig. BT (N.88°E., 3.3 ft.) no blazes or scribing fd. O.B.T.?

No evidence of NW BT from 1921 Cole renewal found.

24" now 24" dia. 1' high rotted oak stump, no blazes or scribing fd., bears S.74°E., 37.5' (agrees w/ rec.) (1961).

17" now 18" dia., 25' D.Fir snag with a fully healed double blaze, bears N.86°W., 44.4' (rec. N.86°W., 46.1' and a 1961 BT tag dist of 45') (1961).

New Accessories

14" dia., ash double blazed and scribed "SW DLC 61 CS BT" bears S.73°W., 5.3'.

9" dia., Poplar double blazed and scribed "SW DLC 61 CS BT" bears N.36½°W., 15.9'.

17" dia., W.Oak double blazed and scribed "SW DLC 61 CS BT" bears N.13°E., 6.9'.

9" dia., Ash double blazed and scribed "SW DLC 61 CS BT" bears S.5°E., 21.6'.

Corner lies in bottom of creek approx. 50' east of road.

Fd. Ok, Feb., 1994 - Kristian DeGroot - 1994-0101

Fd. Ok by Greg Lang 12/1997 - 1999-0030

Fd. Ok by Neil Hibbs 8/2020 - M178-6

Fd. Ok by Neil Hibbs 5/2023 - M178-64