

TOWNSHIP 26 RANGE 06 POINT IDENTIFIER # 200500

PRIMARY CORNER DESCRIPTION Sec. Cor. for 7, 8, 17 and 18

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Original - Elder & Gile, Contract #31 dated April, 1853

Set post cor. to Secs. 7,8,17 and 18, from which

A Y.Oak 13" dia. bears N.32½°E., 132 lks.

A Y.Oak 20" dia. bears S.85½°E., 153 lks.

A Y.Oak 10" dia. bears S.40½°W., 406 lks.

A Laurel 20" dia. bears N.58½°W., 291 lks.

Ben B. Irving - For: J.T. Epperly - July 1926
C.S. 38/205 - M 28-29

No trace of the orig. cor. could be found after a diligent search. Mr. George Winnefred stated that he found one BT several years ago but had looked for it later and failed to find it. The area including this corner has been slashed during the last winter. I relocated this cor. by proportional measurements from the sec. corners next East & West from this corner & from the ¼ sec. cors. next North & South of this cor. For the Corner, I drove an Iron Pipe 2' x 36" in the ground from which:

A 18" Fir bears S.41°30'W., 275.4 ft. mkd. S.18 T26S
R6W BT.

A 30" Fir bears S.14°15'E., 211.0 ft. mkd. S.17 T26S
R6W BT.

and as there were no trees in sight in the north quadrant & as there was a possibility of the above trees being killed when the slash was burned, I set an additional tree as follows:

A 15" W.Oak S.47°45'E., 611 ft. mkd. S17 T26S R6W BT.

This tree is on the bank of the creek running through the draw.

Milo E. Godfrey, Deputy Co. Surveyor - Wm. Stoffel; Mike Darby; Mike Stone - July 1964 - C.S. File 52/87

Found - 1¼" I.P., 2" outside dia..
W.Oak now 24" dia. S.47°E., 611.0 ft. (on creek bank) Shows old axe scar.

Badly burned & rotted Fir stump S.14°E., 211.0 ft.
No marks found.

Badly burned Fir snag S.41°W., 275.4 ft. No mks fd.

New BTs - 14" Madrone S.76°W., 69.4 ft.mkd.T26S R6W S18 CSBT.
(Cont. Next Page)

TOWNSHIP 26 RANGE 06 POINT IDENTIFIER # 200500

PRIMARY CORNER DESCRIPTION Sec. Cor. for 7, 8, 17 & 18

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Found - 12" Madrone S.76°W., 69.4 ft. mkd. T26S R6W S18 CS BT. 13" Madrone S.7½°E. 140.5 ft. mkd. T26SR6W S17 CSBT. No suitable trees near NE of corner.
Dave Edwards, Mar. 1997, found 2" O.D. iron pipe - 1997-0059
DCS0-GIS Corner visitation - 6/16/2004 - Typed: 1/25/2011 - C.S. File 67/33-1 ----- Monument - 2" Comment - needs rehab
David Edwards - Crew: Brant Miller & Eric Springle - Feb. 2, 2026 - C.S. File 65/116-17 ----- Found - 2" outside dia. iron pipe. All previous bearing trees are gone. New - A 7" dia. Fir scribed "S8 BT" bears N.48°E. 12.2 ft An 8" dia Fir scribed "S18 BT" bears S.78°W. 6.0 ft 5.5 ft steel posts are set 2 ft North & 2 ft South. Compass decl. 15°E.
Fd. OK - David Edwards - 3/11/26 - M186-70