

TOWNSHIP 26 RANGE 06 POINT IDENTIFIER # 200540

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 7 & 8

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Original - Elder & Gile, Contract #31 dated April, 1853

Set ¼ sec. post, from which
A Y.Oak 20" dia. bears S.40½°E., 90 lks.
A Y.Oak 24" dia. bears N.43°W., 250 lks.

G.A. McHenry, DCSO - Wit. P.D. Wolford; S. Bowden
Dec. 1921 - (No source reference found - see "Old" corner
renewal book, Vol. 1 Pg. 74)

Set 1" x 18" Iron pipe from which a 36" B.Oak bears S.70¾°E.,
40.5 ft.
A Red Fir 24" dia. bears S.3°E., 34.2 ft.

H. Crowder, Transitman, Co. Engineering Office
May 23, 1951 - C.S. 44/47-7

Found stumps of original bearing trees. Corner in middle of
County Road #6.
Scribed 8" Maple N.30¼°W., 22.6 ft.
10" W.Oak S.32¼°E., 30.0 ft.
Set witness point, 1" I.P. S.46¼°E., 13.5 ft.

Milo E. Godfrey, Deputy; Wm. Stoffel; M. Darby; M. Stone
July 1964 - C.S. File 52/87-64

Found - ¾" Iron pipe with elbow.
Wit. Cor. 13.5 ft. S.46½°E., of ¼ corner.
16" W.Oak S.32¼°E., 30.0 ft. from ¼ cor., shows good
scars.
Maple BT to NW is now gone.
New BTs - D.Fir S.41°W., 36.5 ft. from Wit. Cor. mkd. WC ¼ S
7 CS BT.
¼ Corner is in County Road.

Corner referenced out for Road work, J. Powell, April 5, 1973
C.S. File 57/12

TOWNSHIP 26 RANGE 06 POINT IDENTIFIER # 200540

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 7 & 8

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Douglas Co. Surveyors Office - Gary L. Langlitz - Peter Earle
December 30, 1974 - C.S. File 57/12-8

This corner reset from reference monuments as shown on the attached notes dated 4/5/73. At this time, we find no evidence of the orig. corner or the witness corner, or their accessories. At the true point for the 1/4 corner approx. 2.5 ft. westerly of the centerline of County Rd. #6, we drive a bridge spike, flush with the asphalt pavement from which we mark the following bearing tree and note the following bearing objects:

A 15" W.Oak bears S.69 1/2°E., 80.7 ft. scribed 1/4 S 8 CS BT.
An iron rod with alum. cap attached mkd. "Douglas County Rd. Dpt. R-W 35" at Engineers Station 261+71.71, 35 ft. left of centerline at the westerly R/W fence of Co. Rd.#6, bears S.55°W., 161.17 ft.

An iron rod with alum. cap attached mkd. "Douglas Co. Rd. Dpt. R-W 50" at Engineers Station P.O.C. 264+50, 50 ft. left of the centerline of Co. Rd. #6 & at the westerly R/W fence bears N.23 1/2°E., 128.0 ft.

Compass declination setting: 20° East.

Found bridge spike as recorded. Found accessories as recorded.
Doug. Co. Surveyors Office, R. Smith; S. Flause 1/17/92
C.S. File 64/23-16

DCS0-GIS Corner visitation - 6/23/2004 - Typed: 1/25/2011 -
C.S. File 67/33-1

Comment - (needs) rehab

Fd. Ok by C. Sweeden, 9/2007 - M154-32