

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 17 & 20

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Original - Elder & Gile, Contract #31 dated April, 1853

Set ¼ sec. post, from which
 A Y.Oak 13" dia. bears S.57°E., 15 lks.
 A Y.Oak 13" dia. bears N.17°E., 40 lks.

J.W. Cole, Deputy - April, 1921 - F.B. 50 Pg.54

I renewed this corner from the original bearing trees..
Set a 4 x 4 x 40" Oak post from which the original bearing
trees bear as follows:
 S.57°E., 9.9 ft.
 N.17°E., 30 ft.

James W. Byron, Deputy - D.McFarland; J.Powell
For: Doug. Co. Parks Dept Oct. 26, 1961, C.S. 52/95 & M 21-60

Found - Orig. BT, 13" now 24" B.Oak S.57°E., 9.9 ft. shows
 good scribing on old face "¼S". Orig. N. BT
 down. Pipe set by Waters not found.
Set - Brass cap at corner mkd: County Surveyors Office
 1961 ¼ S17 S20 T26S R6W.
Corner under E.W. fence.
New BTs- 14" Laurel bears S.24°W., 21.0 ft scribed ¼ S20 CSBT
 15" Laurel bears N.55°W., 18.7 ft scribed ¼ S17 CSBT

Doug. Co. Surveyors Office - Randall Smith; Stephen Flauser;
Terrie Franssen - June 25, 1990 - C.S. 64/9-12

Found - A 2½" dia. 1961 DCSO brass cap on a 1¼" O.D. x 36"
 long I.P. is found out of ground.
 13" now 24" dia. 8 ft. high B.Oak snag with a
 partially healed blaze, bears S.57°E., 9.9 ft.
 Original BT (agrees with record)
 Orig. NE BT is gone.
 14" now 13" dia. madrone with a partially healed
 double blaze, illegible scribe marks visible,
 bears S.24°W., 20.2 ft. (Rec. S.24°W., 21.0
 dist. fits center at blaze height.)
 15" now 17" dia. madrone with a partially healed
 double blaze, illegible scribe marks visible,
 bears N.55°W., 18.7 ft. (agrees w/record)
Set - DCSO BC/IP is reset at a point established from BTs.
 The stamping "RESET 1990" is added to brass
 cap. BC/IP now protrudes 9" above ground.
New BTs- 12" dia. madrone double blazed & scribed "¼S20 CS BT
 bears S.23°E., 2.3 ft.
continued next page

