

PRIMARY CORNER DESCRIPTION Sec Cor for 8, 9, 16 and 17

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

Original - Elder & Gile, Contract #31 dated April, 1853  
-----  
Set post cor. to Secs.8, 9, 16 and 17, from which  
    A Y.Oak 18" dia. bears N.73½°W., 25 lks  
    A Y.Oak 14" dia. bears S.75½°W., 102 lks.  
    A Y.oak 8" dia. bears S.72°E., 36 lks.  
    A Y.Oak 20" dia. bears N.31½°E., 119 lks.

O.F. Thiel - For: James Cooper - Dec. 3, 1900 - added  
4/11/2006 - Field Book 114 page 34  
-----  
Set post & rock 20x12x6 & MR

Ben B. Irving - For. J.T. Epperly - July 1926  
C.S. 37/105 - M 28-29  
-----  
Fd mound of rock with old stake in center. Four BTs fd checked  
except in two instances. One dist. 86 lks. instead of 36 lks.  
Other bearing N.62°E., instead of S.72°E. Trees had been  
chopped out & were badly rotted. Replaced trees as follows:  
    A 4" Fir N.5°46'E., 21.9 ft. mkd. S9 T26S R6W BT.  
    A 8" B.Oak S.70°15'E., 21.4 ft. mkd. S16 T26S R6W BT.  
    20" Fir S.56°30'W., 49.5 ft. mkd. S17 T26S R6W Bt.  
    24" Fir N.58°00'W., 75.0 ft. mkd. S8 T26S R6W BT.

Milo E. Godfrey, Deputy - Wm. Stoffel; M. Darby; M. Stone  
July 1964 - C.S. File 52/87-57  
-----  
Found - Rock at Corner.  
    Fir stump (24" when mkd. not 4") N.5¾°E., 21.9 ft.  
        Found scribing "S9".  
    Fir stump S.56½°W., 49.5 ft. shows good scar.  
    B.Oak, now 15" dia. S.70¼°E., 21.4 ft. Shows very  
        good scar. Tree partly uprooted & down, but  
        still alive.  
    D. Fir now 33" dia. N.58°W., 70.5 ft. (Not 75.0 ft.)  
        2 good axe marks visible.  
    Remnant of old Oak N.73½°W., 16.5 ft. still in  
        existence, original BT.  
Set - Brass cap mkd. "County Surveyor's Office 1964  
            T 26 S R 6 W    S 8 | S 9  
                            S 17 | S 16

New BTs - 11" D.Fir N.78°E., 38.5 ft. mkd. T26SR6W S9 CS BT.  
          8" D.Fir S.82°E., 38.3 ft. mkd. T26SR6W S16 CS BT.  
          11" B.Oak S.69°W., 16.4 ft. mkd. T26SR6W S17 CSBT.  
NW tree still good. Cor. is 4 ft. E. of N & S. fence.

TOWNSHIP 26 RANGE 06 POINT IDENTIFIER # 300500

PRIMARY CORNER DESCRIPTION Sec Cor for 8, 9, 16 and 17

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

Greg Solar, L.S. #1331 - For: Walt Loomis - Oct. 1995 -  
M 122-73

-----  
Found - Brass Cap on IP. (See C.S. File 52/87)  
11" D.Fir, N.78°E., 38.5', has been cut flush with  
ground in current logging operation.  
33" D.Fir, N.58°W., 70.5', now a rotten stump.  
D.Fir, S.82°E., 38.3', good condition.  
B.Oak, S69°W., 16.4', good condition.

DCSO-GIS Corner visitation - 6/15/2004 - Typed: 1/26/2011 -  
C.S. File 67/33-1

-----  
Monument - BC/IP 1.25"  
Comment - (needs) rehab