

TOWNSHIP 26 RANGE 06 POINT IDENTIFIER # 400400

PRIMARY CORNER DESCRIPTION Sec. Cor. for 15, 16, 21 & 22

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Original - Elder & Gile, Contract #31 dated April, 1853

Set post cor. to Secs. 15,16,21 & 22, from which
 A Y.Oak 16" dia. bears S.42½°W., 64 lks.
 A W.Oak 24" dia. bears N.13½°W., 52 lks.
 A W.Oak 14" dia. bears N.56¼°E., 61 lks.
 A Y.Oak 14" dia. bears S.67½°E., 82 lks.

JW Cole, Deputy Co. Surveyor - May 1921 - FB 50 Pg. 63M 1 - 69

Set an Iron pipe also an Oak post from which the original
BTs bear as follows:
 A B.Oak alive & standing S.22°30'W., 42.2 ft.
 A stump showing scribe marks S.67°30'E., 54.1 ft.
 A W.Oak BT standing N.56°45'E., 40.3 ft.
 A W.Oak N.13½°W., 34.1 ft.

James W. Byron, Deputy - M.Godfrey; S.A. Bilow
Oct. 28, 1958 - C.S. File 49/121-1

Found - Orig. 24" now 32" W.Oak N.13½°W., 34.3 ft. I open &
 find good scribing "S BT".
 Orig. 16" B.Oak, record S.42½°W., 42.2 ft. I find
 should be S.22½°W., 42.2 ft. which is the same
 bearing Cole recorded, 1921. I open this BT &
 find good scribing "T26S S21 BT".
 No trace of orig. SE or NE BT.
Set - Brass cap at cor. mkd: S16|S15 T26S R6W County
 S21|S22
Corner is under E-W wire fence.
New BTs - 9" W.Oak bears N.52°W., 65.4 ft. scribed S16 T26S
 R6W CS BT.
 15" R.Fir bears S.13°E., 69.2 ft. scribed S22 T26S
 R6W CS BT.
 10" W.Oak bears S.38°W., 5.0 ft. scribed S21 T26S
 R6W CS BT.
 18" B.Oak bears N.71°E., 71.0 ft. scribed S15 T26S
 R6W CS BT.

Found OK, DCSO M.E.G. June 1964 C.S. File 52/87-32

Douglas Co. Surveyors Office - Stephen J. Flause - John Pike
- 5/24/2006 - C.S. File 67/14-13

Found - 1" O.D. IP in good condition, firmly set & plumb,
 top is flush w/ground. This appears to be
 Cole's 1"x30" IP from 1921, cont. next pg

TOWNSHIP 26 RANGE 06 POINT IDENTIFIER # 400400

PRIMARY CORNER DESCRIPTION Cor. Secs. 15, 16, 21, & 22

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

cont. . . . reference to which was crossed out in Byron's 1958 renewal field notes.
No evidence of 1958 brass cap is fd.
Evidence of one OBT is fd: A distinct root-hole is located near the rec. bearing & dist. from the orig. NW W.Oak BT.
All 4 1958 Byron renewal trees are fd.
9" W.Oak now a 14" DBH W.Oak with a fully healed double blaze (unusually high upper blaze) bears N.55½°W., 66.2 ft (rec. N.52°W. 65.4 ft)
15" R.Fir now a 26" DBH D.Fir with a fully healed double blaze bears S.13°E., 68.8 ft. (rec. S.13°E., 69.2 ft)
10" W.Oak now a 15" DBH W.Oak with a fully healed double blaze bears S.48°W., 6.0 ft. (rec. S.38°W., 5.0 ft)
18" B.Oak now 19" DBH B.Oak with a fully healed double blaze bears N.71°E., 69.2 ft. (rec. N.71°E., 71.0 ft possibly a slope measurement)
New - Due to condition & quality of fd. monument, we leave as is. We tag & flag fd. BTs.
Note - Monument is directly under a dilapidated metal gate panel in an East-West fence line & just west of a fence running North. Corner is on very gently sloping South-East running ridge.

FD. Ok by D. Edwards 11/2006 - M151-66