

TOWNSHIP 26 RANGE 06 POINT IDENTIFIER # 540700

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Sec. 2; & 35 of T25-6

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Original - Elder & Gile, Contract #31 dated April, 1853

Set ¼ sec. post, from which
A Fir, 8" dia. bears N.32°E., 46 lks. dist.
A Cedar 16" dia. bears S.21°E., 103 lks. dist.

Milo E. Godfrey's Crew - Vernon Tracy; Mike Stone
June 27, 1963 - C.S. File 49/123

Found - 46" Fir stump N.32°E., 30.4 ft. Cut open & found one
scribe mark "l". Tree had been opened
previously & grown over again. Balance of upper
face rotted.

No trace of Cedar to S.E.
Set - Brass cap at cor. mkd: County Surveyors Office 1963
T25S R6W ¼ S 35
S 2

New BTs - 15" W.Fir N.48½°E., 66.2 ft. mkd. ¼ S35 CS BT.
9" D.Fir S.58°W., 78.5 ft. mkd. ¼ S 2 CS BT.

Note - Corner falls in E. & W. fence line 33 ft. west of small
stream.

Found OK by Mark Smalley, LS # 2354 - For: Roseburg Resources
Co. - Feb & Mar 1993, M 117-7.

Mark Smalley, July 1995, M 119-67

Found - 1963 County BCIP
26" fir N.48½°E., 66.2' healed.
20" fir S.58°W., 78.5' healed.
New BT's- 18" fir N.82°W., 21' "¼ S BT"
10" fir S.35°E., 18.8' "¼ S BT"