

PRIMARY CORNER DESCRIPTION Sec Cor for 1, 2, 11 and 12

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Original - Elder & Gile, Contract #31 dated April, 1853

Set post cor. to Secs. 1, 2, 11 and 12, from which

A Y.Oak 30" dia. bears N.33 $\frac{3}{4}$ °W., 138 lks.

A W.Oak 8" dia. bears N.62°E., 144 lks.

A W.Oak 9" dia. bears S.85°E., 138 lks.

A Y.Oak 18" dia. bears S.13°W., 107 lks.

Milo E. Godfrey, Deputy - Wm. Stoffell; Mike Darbey; Mike Stone - May 1964 - C.S. File 52/87-14

Found - W.Oak snag S.85°E., 91.1 ft. opened & found good reverse scribing, face nearly all rotted. Badly rotted remnants of uprooted Oak S.13°W., 70.6 ft., too far gone to find markings. No trace found of NE or NW trees.

Set - Brass cap mkd. County Surveyors Office 1964 T 26 S
R6W S 2|S 1
S11|S12

New BTs - 8" D.Fir N.31°E., 14.9 ft. mkd. T26S R6W S1 CS BT.
8" D.Fir S.36°E., 18.6 ft. mkd. T26S R6W S12 CS BT.
12" D.Fir S.20°W., 23.4 ft. mkd. T26SR6W S11 CS BT.
7" D.Fir N.82°W., 22.2 ft. mkd. S2 CS BT.

A 3-way fence corner, fences East, West & South, bears S.62°W., 5.5 ft.

Found Brass Cap - Robert Dolan, June 1993, Partition Plat 1993-0044

Mark Smalley, July 1995, M 119-67, for: Roseburg Resources

Found - 1964 County BCIP

BT's Fd.- W. Oak snag fallen over badly rotten

14" fir stump, N.31°E., 14.9'

18" fir stump, S.20°W., 23.4'

21" fir, N.82°W., 22.2', healed

14" fir, S.36°E., 18.6', healed

New BT's- 14" fir, S.77°E., 41.5', "S 12 BT"

11" fir, S.46°E., 93.6', "S 1 BT"