

TOWNSHIP 26 RANGE 06 POINT IDENTIFIER # 700700

PRIMARY CORNER DESCRIPTION Tsp. Corner (NE Cor. Section 1)

Alias 048010 Description NE Cor. Otey DLC #48
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Original - Elder & Gile, Contract #31 dated April, 1853

Set Post cor. to Tps. 25 & 26, South between ranges 5 & 6 W.
Drove charred stake and raised mound with trench and
pits as per instructions.

Milton L. Baldy - For Don Calpin & O.C. Seiter - "Oregon Pear
Co. Plat A" (now vacated) Volume 3 Page 22 - Jan. 1911

Set Galv. I.P. 2" x 36", driven 6" below the surface at the NW
corner Section 6.

James W. Byron, For: Ed Russell, April 1955 C.S. File 47/12

Found - 1½" I.P. at fence intersection. Use 1½" I.P. for
Sec. cor. (See vacated Plat, Oregon Apple &
Pear Co. Plat A Vol. 3 Pg. 22, Initial Point.)
All orig. BTs gone. (I could find none ever listed. 8/91 V.L.)
Blazed & Scribed:
10" R.Fir N.17°E., 146.0 ft. S31 T26S R5W CS BT.
16" R.Fir (stool of) 600.0 ft. S.84°E., S6 T26S
R5W CS BT.
No other trees near.

U.S. BLM - Group #502, C. Albert White & Donald R. Beck,
Cadastral Surveyors - May 3-24, 1963 (Co. Survey Records,
Volume 32 Page 13361-62)

Point determined at the intersection of old wire fences which
extend N. and W., at the SE. corner of an old orchard, from
which bearing trees mkd. by J.Byron in 1955:

A Fir 18" dia. bears N.20°E., 224 lks. dist. mkd. with a
healed blaze, facing the corner.

A Fork of a Fir 25" dia. bears S.85°E., 910 lks. dist.
mkd. with a healed blaze, facing the corner.

At the corner point Set:

An iron post 28" long 2½" dia. 24" in the ground with
brass cap mkd.

T 25 S
R 6 W R 5 W
S 36 | S 31
S 1 | S 6
T 26 S
1963

No suitable trees available in secs. 1 and 36 within limits.

TOWNSHIP 26 RANGE 06 POINT IDENTIFIER # 700700

PRIMARY CORNER DESCRIPTION Tsp. Corner (NE Cor. Section 1)

Alias 048010 Description NE Cor. Otey DLC #48
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Found OK, D. Bentz, November, 1986, M 103-30
Found OK, D. Bentz, April, 1988, M 106-4
Found OK, M. Smalley, July 1995, M 119-67

Douglas Co. Surveyors Office - Randall W. Smith - Stephen J. Flause - 2/11/98 - C.S. File 64/79-26

Found - 3½" dia., brass cap on a 2½" O.D. iron pipe, protrudes 5" above ground. 1963 BLM
10" now 41" dia., D.Fir with fully healed blazes, bears N.18½°E., 146.0 ft. (1955 rec. N.17°E., 146.0 ft.) 1955 DCSO
16" now 30" dia., triple trunked down D.Fir with a fully healed blaze root hole near. (Rec. S.84°E., 600.0 ft) 1955 DCSO
New BTs- 30" dia., D.Fir, bark scribed "T25S R6W S36 CS BT" bears N.13°W., 427.0 ft.
30" dia., D.Fir, bark scribed "T25S R6W S36 CS BT" bears N.60°E., 324.0 ft.
Note - Corner lies at the intersection of fences running East, West, & North. No trees south of line. See sketch in file.

DCSO-GIS Corner visitation - 7/7/2004 - Typed: 01/25/2011 - C.S. File 67/33-1

Monument - BC/IP 1.25"
Comment - ok

Fd. BC by M. Schulze, 11/2012 - M164-47