

TOWNSHIP 26 RANGE 07 POINT IDENTIFIER # 046030

PRIMARY CORNER DESCRIPTION SW Cor. Gillham DLC #46

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

<p>Original - J.A. Burnett, Contract #75 dated Nov. 22, 1856 ----- Set a post as per instructions, from which A B.Oak 16" dia., bears N.45°E., 297 lks.</p>
<p>Doug. County Surveyors Office - James Byron; Milo Godfrey; Clete Putnam - May 4, 1960 - C.S. File 49/129-5 ----- Found - Orig. 16" now 48" B.Oak N.45°E., 196.0 ft. I open & find good scribing "R7WS". Set Brass cap at cor. mkd: County Surveyor's Office, 1960 S. W. Cor. D.L.C. 46 T26S R7W New BTs - 5" W.Oak bears N.45°E., 27.5 ft. scribed CL 46 CSBT 12" W.oak bears N.11°E., 54.8 ft. scribed DLC 46 SW CS BT.</p>
<p>Douglas County Surveyors Office - Randall Smith & Stephen Flause - May 8, 1997 - C.S. 64/74-29 ----- Found - 2½" dia. Brass cap on a 1½" O.D. Iron pipe protrudes 13" above ground, bent and leaning NW'LY of plumb. (1960) ** 16" now 50" dia. B.Oak, with a previously opened unhealed blaze no scribing visible, bears N.43°E., 196' (rec. N.45°E., 196') OBT. 5" now 13" dia. W.Oak, with a fully healed blaze, bears N.43°E., 27.5' (rec. N.45°E., 27.5') 1960 12" now 19" dia. W.Oak, with a fully healed single blaze, bears N.9°E., 54.8' (rec. N.11°E., 54.8') 1960 Set- BC/IP is straightened and returned to plumb position set 6" below ground. ½" I.D. iron pipe protrudes 2" above ground, bears N.1°W., 63.6'. ¾" I.D. iron pipe protrudes 8" above ground, bears N.34°E., 52'.</p>
<p>Fd. ok by D. Beedle - 10/1998 - M 130-44 Fd. Ok by K. DeGroot, 9/5/2006 - M151-41</p>
<p>**Per phone call w/land owner this tree reported as cut down 10/11/2007 - DCS0</p>
<p>FD BC 6/2018 by Jody Frasier - M174-48</p>
<p> </p>