

PRIMARY CORNER DESCRIPTION 1/4 Cor. Sec. 19; & 24 of T26-8

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

Original - Dennis Hathorn, under Contract #57 dated April 12 1855 (DCSO records, Volume 11 Page 4590)

-----  
Set ¼ sec. post, from which  
    A Fir 24" dia., bears N.38°W., 15 lks. dist.  
    A Fir 12" dia., bears N.10°E., 58 lks. dist.

-----  
GLO survey by S.C. Flint, under Contract #392 dated May 1881 (DCSO records, Vol. 11 Page 4620)

-----  
Quarter post not found. Witness trees found. Made new Cedar post, 3 ft. long 3" sq. and set firmly in the ground, from which  
    A Fir 24" dia., bears N.38°W., 15 lks. dist.  
    A Fir 12" dia., bears N.10°E., 58 lks. dist.

-----  
BLM survey by Zirpel and Martin, under Group #'s 350 & 357 Survey, April/May 1959 - (DCSO records, Volume 29 Pages 12535-36)

-----  
The 1/4 Corner determined at record distance from the remains of the original bearing trees:

- A sawed Fir stump 31" dia., bears N.3¾°E., 58 lks. dist. with illegible scribe marks visible on partly opened blaze. (Rec. bearing N.10°E.)
- A burned and rotted Fir snag, 36" dia., bears N.29°W., 15 lks. dist., with overgrowth BT and scribe mark B found in the center of the rotted trunk. (Rec. bearing N.38°W.)

At the corner point, Set an Iron post, 28" long, 2½" dia., 26" in the ground, with brass cap mkd. T26S

R8W R7W

¼

S 24|S 19

1959

from which

An iron post, 28" long, 2½" dia., set 26" in the ground, for a reference monument, bears N.40½°E., 13 lks. dist., with brass cap mkd. T26S R7W ¼ S19 RM 1959 and an arrow pointing to the corner.

An iron post, 28" long, 2½" dia., set 26" in the ground, for a reference monument, bears S.65°W., 11 lks. dist., with brass cap mkd. T26S R8W ¼ S24 RM 1959 and an arrow pointing to the corner.

No suitable bearing trees are available.

TOWNSHIP 26 RANGE 07 POINT IDENTIFIER # 100340

PRIMARY CORNER DESCRIPTION 1/4 Cor. Sec. 19; & 24 of T. 26-8

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Bureau of Land Management resurvey by Peterson & Berry, under Group #739 - Survey May/July 1971 (DCSO records, Volume 37 Pages 15197-98)

-----  
1/4 Cor. monumented with an iron post, 2½" dia., firmly set, protruding 4" above ground, with 1959 brass cap.

from which the remains of the original bearing trees

A sawed Fir stump 31" dia., bears N.8¾°E., 58 lks. dist., with illegible scribe marks visible on partially opened blaze.

A burned & decayed fir snag, 36" dia., bears N.29°W., 15 lks. dist., with scribe marks BT in negative on overgrowth, and scribe mark B found in the center of decayed trunk.

and new bearing trees

A Fir 6" dia., bears N.43°E., 56 lks. dist., mkd. 1/4 S19 BT.

A Fir 6" dia., bears N.49½°W., 34½ lks. dist., mkd. 1/4 S24 BT.

Found OK by T. Hostetter, Nov. 1998 - M131-5