

PRIMARY CORNER DESCRIPTION 1/4 Cor. for secs. 31 and 32

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Original - S.C. Flint, under Contract #392 dated May 1881
(DCSO records, Volume 11 Page 4630)

Set a Laurel post for ¼ sec. cor, 3 ft. long, 4" sq., from
which
 A Fir 30" dia., bears S.60°E., 7 lks. dist.
 A Fir 12" dia., bears S.45°W., 36 lks. dist.

Bureau of Land Management by Peterson, Berry, etal, under
Group #'s 744 and 838. Survey May 1971/Aug. 1974 (DCSO
records, Volume 37 Pages 15181-82)

Point for the ¼ sec. cor., at proportionate distance; there
is no remaining evidence of the original corner.
Set an Iron post 28" long 2½" dia., 22" in the ground, with
 brass cap mkd. T 26 S R 7 W
 1/4
 S 31|S 32
 1974
from which
 A Fir 7" dia., bears S.10 3/4°W., 70 lks. dist., mkd. ¼
 S31 BT.
 No other suitable trees available within limits.
Corner is located on top of spur ridge, bears N.40°E. and
S.40°W.

Tony Hostetter - For: Weyerhaeuser Co. - Nov. 1999 - M 134-63

Found - 2½" brass cap set by BLM in 1974, from which
 24" Fir, face evident, tag missing, bears
 S.11°05'W., 44.7 ft. to new spike. (New BT Tag)
New BTs - 17" Fir, scribed "S32 ¼ BT" bears N.46°E., 16.3 ft.
 to spike.
 14" Fir, scribed "S32 ¼ BT" bears S.52°E., 6.1 ft.
 to spike.
 11" Fir, scribed "S32 ¼ BT" bears N.32°W., 7.2 ft.
 to spike.

Fd ok BLM Dependent resurvey by Timothy J. Moore, Cadastral
Surveyor & Robert Browning, Surveying Technician under Group
#1990, surveyed 2001/2002 (DCSO rec. Vol. 54 pg(s) 21031-2)

Fd as described by Moore & Browning in 2001-2, by Timothy J.
Moore, Cadastral Surveyor & Robert Browning, Surveying
Technician under Group #2100, surveyed June 2006 (DCSO rec.
Vol. 56 pg 22269 & Plat 2011-1, T26-7)