

TOWNSHIP 26 RANGE 07 POINT IDENTIFIER # 200340

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 19 and 20

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

Original - S. C. Flint, under Contract #392 dated May 1881  
(DCSO records, Volume 11 Page 4634)

-----  
Set Fir post, 3 ft. long, 4" sq., from which  
    A Fir 36" dia., bears S.80°E., 50 lks. dist.  
    A Fir 25" dia., bears N.35°W., 32 lks. dist.

Bureau of Land management resurvey by Roseberry, under Group  
#696. Survey, July 1969 (DCSO records, Volume 36 Pg. 14861-62)

-----  
1/4 Corner secs. 19 and 20, determined at record distance from  
the remaining original bearing trees:

    A sawed Fir stump 60" dia., bears S.69°E., 50 lks. no  
    marks remaining on burned blaze. (Record S. 80° E.)

    A sawed fir stump, 48" dia., bears N.23°W., 32 lks. no  
    marks remaining on burned blaze. (Record, N.35°E.)

At the corner point, set an iron post 28" long, 2½" dia.,  
24" in the ground, with brass cap mkd:

    T 26 S R 7 W

        1/4

        S 19|S 20

        1969

from which new bearing trees

    A Fir 3" dia., bears N.49°E., 29½ lks. mkd. X BT.

    A Fir 5" dia., bears N.55°W., 43 lks. mkd. 1/4 S19 BT.

BLM 1971-74 resurvey by Peterson, etal, added "1974" to  
brass cap. (DCSO records, Volume 37 Pg. 15190)

FD. Ok, BLM Dependent resurvey by Timothy J. Moore, Cadastral  
Surveyor & Robert Browning, Surveying Technician under Group  
#1990, surveyed 2001/2002 (DCSO rec. Vol. 54 pg(s) 21025)

Fd. Ok by Lloyd Tolbert, May 2005 - M147-68