

TOWNSHIP 26 RANGE 07 POINT IDENTIFIER # 240100

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Sec. 32; & 5 of T27-7

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

<p>Tony Hostetter - For: Weyerhaeuser Co. - May 2001 - C.S. File 65/37-11</p> <p>-----</p> <p>Found - 1961 brass cap by DCS0 as described by BLM in 1974. 36" Fir stump OBT, & both BTs mkd. by BLM in 1974 are present.</p> <p>New BTs- 10" Fir scribed "S32 ¼ BT" WEYCO tag, bears N.65°45'E., 7.4 ft. to spike placed in root collar below scribing.</p> <p>12" Fir, scribed "S5 ¼ BT" WEYCO tag, bears S.4°E., 20.9 ft. to spike placed in root collar below scribing.</p> <p>17" Fir, face evident (BLM tag), WEYCO tag, bears S.11°19'W., 29.8 ft. to spike placed in root collar below face.</p>
<p>Fd. Ok on BLM Dependent resurvey by Timothy J. Moore, Cadastral Surveyor & Robert Browning, Surveying Technician under Group #1990, surveyed 2001/2002 (DCS0 rec. Vol. 54 pg(s) 21010-11)</p>
<p>Ron Quimby - For: Weyerhaeuser - June 2017 - M173-35</p> <p>-----</p> <p>Found - Brass cap per 1961 renewal</p> <p>19"x6' tall hemlock stump bears N.19°E., 122.1' - healed double blaze</p> <p>36" sawed fir stump bears S.58°E., 8.6' partially visible scribe</p> <p>17" fir bears S.4°E., 20.9' (to spike in root collar) - healed blaze</p> <p>20" fir bears S.11°W., 29.8' (to spike in root collar) - healed blaze</p> <p>New BT - 16" fir bears S.65°W., 15.2' - scribed "¼ S5 BT"</p>
<p> </p>