

TOWNSHIP 26 RANGE 07 POINT IDENTIFIER # 400600

PRIMARY CORNER DESCRIPTION Sec. cor. for 3, 4, 9 and 10

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

Original - Dennis Hathorn, under Contract #57 dated April 12, 1855 (DCSO records, Volume 11 Page 4613)

-----  
Set Post cor. secs. 3, 4, 9 and 10, from which  
A Hemlock 10" dia., bears S.4°W., 25 lks. dist.  
A Hemlock 12" dia., bears N.13°E., 20 lks. dist.  
A Hemlock 6" dia., bears S.35°E., 45 lks. dist.  
A Fir 8" dia., bears N.75°W., 31 lks. dist.

-----  
GLO survey by S.C. Flint, under Contract #392, dated May 26, 1881 (DCSO records, Volume 11 Page 4628)

-----  
Old post gone, but witness trees found. Made new Cedar post and set the same.

-----  
Doug. County Surveyors Office - James W. Byron, Deputy - Milo Godfrey; Clete Putnam - August 26, 1959 - C.S. File 49/129-9

-----  
Found - Orig. 6" now 32" W.Fir S.35°E., 29.7 ft., center rotted but shows good reverse scribing "2 S W 0".

Orig. 10" now 34" W.Fir S.4°W., 16.5 ft., now down, center rotted but shows parts of old face, no scribing found.

No trace of orig. NW or NE BTs.

Set Brass cap at cor. mkd:  $\frac{S\ 4\ S\ 3}{S\ 9\ S\ 10}$  T26S R7W County Surveyor Office, 1959

I find steel post said by Neilson to be Boyer's corner, bears S.71½°E., 18.6 ft. from brass cap. Reset steel post alongside brass cap.

New BTs - 14" R.Fir bears N.39½°E., 27.8 ft. scribed S 3 T26S R7W CS BT.

6" W.Fir bears N.65°W., 30.8 ft. scribed S 4 CS BT.

12" W.Fir bears S.60°W., 31.6 ft. scribed S9 T26S R7W CS BT.

32" W.Fir bears S.35°E., 29.7 ft. scribed S10 T26S R7W CS BT.

-----  
Bureau of Land Management resurvey by Roseberry & Garrison under Group #357 - Survey June/Aug. 1967 (DCSO records, Volume 34 Pages 14281-82)

-----  
(Cont. Next Page)

PRIMARY CORNER DESCRIPTION Sec. Cor. for 3, 4, 9 and 10

Alias	Description
_____	_____
_____	_____
_____	_____
_____	_____

The cor. of secs. 3, 4, 9 and 10, perpetuated and recorded by James Byron, Deputy, in 1959, monumented with an iron post, 1" dia., protruding 16" above the ground, firmly set with 1959 BC from which the remaining original bearing tree

A root hole, bears S.35°E., 45 lks. dist., with an up-rooted and sawed fir stump, 30" dia., with fragmentary scribe marks visible on partially rotted blaze. and bearing trees mkd. by Byron in 1959

A Fir 17" dia., bears N.41°E., 42½ lks. dist. with a healed blaze.

A Fir 12" dia., bears S.60°W., 48½ lks. dist., with a healed blaze.

A Fir 9" dia., bears N.66¼°W., 47 lks. dist., with a healed blaze.

and a new bearing tree

A Fir 10" dia., bears S.62½°E., 269½ lks. dist., mkd. T26S R7W S10 BT.

Doug. County Surveyors Office - Larry E. Monrean, Deputy - R.W. Smith; S.J. Flause - Aug. 17, 1984 - C.S. File 62/21-21

Found - (Original post not found)  
Found a 1" I.P. with 1959 brass cap, properly mkd. Remains of roots at record bearing & distance to orig. 6" Hemlock, S.35°E., 20.5 ft.  
No other original evidence found.

14" now 22" Fir with well healed double blaze bears N.39½°E., 27.8 ft. (Rec. BLM, N.41°W., 28.0 ft.) This tree to be completely removed in pasture clearing.

6" Fir at record N.65°W., 30.8 ft., is dead & down.

12" W.Fir now a 10" snag with "T26S R7W S9 CS BT" scribed on partly healed blaze, bears S.60°W., 31.0 ft. (BLM rec. 31.0 ft.; Byron calls 31.6 ft. checks well to center of trunk at top of blaze)

5" Fir 10" now 16" bears S.62½°E., 177.9 ft. Has a well healed blaze. (BLM)

Set - We reset the noted found brass cap at corner position. The monument now protrudes 5" above ground level.

New BTs - 16" W.Fir double blazed & scribed "T26S R7W S9 CSBT" bears N.58½°E., 140.0 ft.

14" W.Fir double blazed and scribed "T26S R7W S9 CS BT" bears S.61½°W., 33.0 ft.

(Cont. Next Page)

TOWNSHIP 26 RANGE 07 POINT IDENTIFIER # 400600

PRIMARY CORNER DESCRIPTION Sec. cor. for 3, 4, 9 and 10

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

14" D.Fir double blazed and scribed "T26S R7W S9 CS BT" bears S.26°W., 28.2 ft.  
Clearing for pasture is in progress. Fences are to run North, West and South from corner when clearing is completed. 72 ft. East to dirt road.

BLM Dependent resurvey by Timothy J Moore Cadastral Surveyor & Robert H Browning, Surveying Tech. under Group #2075, surveyed April/June 2005 (DCSO rec. Vol. 56 pg(s) 22081-2)  
-----  
The cor. of secs. 3, 4, 9, & 10, monumented with an iron pipe, 1" dia., firmly set, projecting 4" above the ground, with brass cap (properly) mkd.  
from which accessories recorded in the Douglas County Surveyors Record of Government Corners Renewed the remains of the remaining BT mkd. by the Douglas County Surveyors Office, in 1959, reported by Roseberry and Garrison  
A fir snag, 11" dia. bears S.60°W., 32.0 ft. with scribe marks T26S R7W S9 CS BT visible on open blaze.  
and a bearing tree mkd. by Roseberry and Garrison  
A fir, 33" dia., bears S.63¼°E., 177.9 ft., with a healed blaze. (Record, S.62½°E.)  
and the remains of bearing trees mkd. by the Douglas County Surveyors Office, in 1984,  
A sawed fir stump, 22" dia., bears N.58½°E., 139.8 ft., with scribe marks BT visible on partially healed blaze.  
A fir, 24" dia., bears S.24½°W., 28.9 ft., with a healed double blaze.  
A fir, 23" dia., bears S.61¾°W., 33.6 ft., with a healed double blaze.  
Corner is located, north, 0.5 ft., of a fence cor., with woven wire fences extending, south and west.