

PRIMARY CORNER DESCRIPTION Sec. Cor. for 3 & 4; 33 & 34 of T25-7

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

Original - Dennis Hathorn, under Contract #57 dated April 12, 1855 (DCSO records, Volume 9 Page 3856)

-----  
Set post cor. of secs. 3, 4, 33 and 34, from which  
A W.Oak 30" dia., bears N.14°E., 17 lks.  
A W.Oak 18" dia., bears N.15°W., 47 lks.  
A B.Oak 24" dia., bears S.75°E., 43 lks.  
A B.Oak 9" dia., bears S.32°W., 35 lks.

-----  
GLO retracement by A.R. and S.C. Flint, under Contract #392 dated May 26, 1881 (DCSO records, Volume 9 Page 3900)

-----  
Old post gone. Made new post 40" long, 4" sq. and set firmly in the ground with Hathorn's trees present.

-----  
Edwin S. Woodford - Wit: Marr Linehart - August 1946  
C.S. File 42/119

-----  
Found one old BT:  
24" Oak S.75°E., 43 lks. (tree now 36") Found reverse of scribe marks in cut out slab.  
Set a 1" x 30" steel shaft set for corner.  
New BT - 15" Fir S.30½°E., 7.7 ft.

-----  
Doug. County Surveyors Office - Michael Stone; Jack Heritage  
April 13, 1966 - C.S. File 54/10-4

-----  
Found - 1" x 30" steel shaft set by Woodford.  
15" now 24" D.Fir S.30½°W., 7.7 ft. (not S.30½°E)  
24" now 38" orig. B.Oak S.75°E., 24.8 ft.  
Set Brass cap alongside shaft, mkd: County Surveyors Office  
1966

-----  
New BTs - 16" D.Fir N.56°E., 71.4 ft. mkd. T25SR7W S34 CS BT.  
5" B.Oak N.18°W., 31.0 ft. mkd. S 33 CS BT.  
Corner is N.30°E., 9 ft. from a N-S-W fence corner on a moderate north slope about 80 ft. south of a creek.

-----  
Cont. Next Page

PRIMARY CORNER DESCRIPTION Sec. Cor. for 3 & 4; 33 & 34 of T. 25-7

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

Bureau of Land Management resurvey by G. Popken, under Group #869. Survey May/July 1975 (DCSO record, Volume 37 Page 15303)

-----  
The corner, perpetuated and recorded by E.S. Woodford, in 1947, when remains of the original corner accessories were in existence. The cor. was subsequently perpetuated and recorded by M. Stone in 1966, and monumented with an iron post, 1" dia. firmly set, projecting 12" above ground with brass cap.

from which the remains of a bearing tree by Woodford  
A sawed fir stump, 24" dia., bears S.30½°W., 13 lks. dist., with healed double blaze.  
and a new bearing tree

A Fir 14" dia., bears S.66°E., 145½ lks. dist. mkd.  
T26S R7W S3 BT.

No other suitable trees available within limits  
Corner is located at junction of fences, extending S. & W.

-----  
Doug. County Surveyors Office - Randall Smith; Stephen Flauser; Terrie Franssen - Jan. 17, 1991 - C.S. File 64/13-3

-----  
Found - 2½" dia. 1966 DCSO brass cap on a 1½" O.D. I.P., protruding 14" above ground.  
1 1/8" O.D. axle shaft protrudes 3" above ground.  
Axle shaft is south 0.4 ft. from brass cap.  
15" now 24" dia. 5 ft. high D.Fir stump with a fully healed double blaze, bears S.25°W., 8.6 ft.  
(Record, S.30½°W., 8.6 ft. in BLM resurvey)  
14" now 20" dia., D.Fir with a fully healed single blaze, bears S.71½°E., 96.0 ft. (Rec. S.66°E., 96.0 ft.) 1975 BLM.

1966 BTs are gone.

New BTs - A multi-trunked Elder berry double blazed and scribed "X BT" on 12" dia. near trunk, bears N.41½°E., 83.9 ft.

5" dia. B.Oak double blazed & scribed "X BT" bears S.78°W., 17.4 ft.

7" dia. pistol butt Maple double blazed & scribed "T25S R7W S33 CS BT" bears N.59°W., 10.4.5 ft. to center of trunk at upper blaze.