

PRIMARY CORNER DESCRIPTION Sec. Cor. for 22, 23, 26 and 27

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

Original, Dennis Hathorn, Under Contract #57 dated April 12, 1855 (DCSO records, Volume 11 Page 4604)

-----  
Set post, cor. secs. 22, 23, 26 and 27, from which  
A B.Oak 10" dia., bears S.35°W., 69 lks. dist.  
A B.Oak 12" dia., bears S.20°E., 36 lks. dist.  
A B.Oak 5" dia., bears N.56°W., 35 lks. dist.  
A B.Oak 14" dia., bears N.50°E., 130 lks. dist.

J.H. Wolford, Surveyor - Wit. B.A. Lane, Jas. F. Jeffries  
Sept. 13, 1934 - C.S. File 18/54

-----  
Set from old BT in section 23. Other trees gone.  
Set 1½" x 18" Pipe. Marked the following new BTs:  
Fir 20" dia., bears S.25°E., 38.0 ft.  
Fir 24" dia., bears N.62½°E., 20.5 ft.  
W.Oak 14" dia., bears N.80¾°W., 107 ft.  
No tree available in section 27.

Doug. County Surveyors Office - Vernon Tracy; Mike Stone; Jack Heritage - March 1966 - C.S. File 54/23-5

-----  
Found - 1½" I.Pipe as recorded by Wolford.  
24" now 25" Fir stump N.62½°E., 20.5 ft., find "BT" scribe.  
14" now 16" W.Oak N.80¾°W., 107 ft., alive, "S" scribe visible on partially healed blaze.  
Set Brass cap at cor. mkd: County Surveyor's T26S S22|S23 R7W  
Office, 1966 S27|S26  
New BTs - 24" Cedar S.22°E., 136.6 ft. mkd: T26S R7W S26 CSBT  
12" B.Oak S.7°E., 59.5 ft. mkd: T26S R7W S26 CS BT.  
No trees available in sections 23 or 27.  
Corner falls at 4-way fence corner, N.E.S.W. Find rotted remains of possible original SE BT.

Bureau of Land Management resurvey by Peterson, etal, under Group #'s 744 and 838 - Survey May 1971-Aug. 1974 (DCSO records, Volume 37 Page 15167)

-----  
(Found 1966 Co. brass cap and 5 BTs.)  
Add marks BLM 1974 to brass cap.

Fd. Brass cap & **NO** BTs by H. Stockhoff- Jan. 1994 - M118-23

continued next page

TOWNSHIP 26 RANGE 07 POINT IDENTIFIER # 500300

PRIMARY CORNER DESCRIPTION Sec. Cor. for 22, 23, 26 and 27

Alias	_____	Description	_____
Alias	_____	Description	_____
Alias	_____	Description	_____
Alias	_____	Description	_____

Douglas County Surveyors Office - Randall Smith & Stephen  
Flause - 5/1/96 - C.S. 64/66-18

-----  
Found - 2½" dia. brass cap on a 1½" O.D. Iron pipe protrudes  
1" above ground.

NOTE: 1974 BLM survey said that they added marks to  
BC "1974" BLM, none found.

24" now rotted to ground Fir, bears N.62½°E., 20.5'.

15" dia. W.Oak, with a fully healed blaze, bears  
N.81½°W., 107.5'.

45" dia. 1½' high Cedar stump, with a fully healed  
lower blaze, bears S.22°E., 136.6'.

27" dia. B.Oak, with a fully healed double blaze,  
bears S.5°E., 59.5'.

12" B.Oak, now depression in ground, bears S.20°E.,  
23.8'.

New BTs- 8" B.Oak, double blazed and scribed "T26S R7W S22 CS  
BT", bears N.14°W., 48.2'.

29" D.Fir, double blazed and scribed "T26S R7W S23  
CS BT", bears N.15¼°E., 139.1'.

Corner lies at the intersection of a 4 way fence corner.