

PRIMARY CORNER DESCRIPTION Cor. Secs 12, 13; 7 & 18 T26-6

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

Original - Elder & Gile, Contract #31 dated April, 1853  
-----

Set post cor. to sec. 7,12,13, & 18, from which

- A Y.Oak 10" dia. bears S.20°E., 54 lks.
- A Y.Oak 14" dia. bears N.67½°E., 63 lks.
- A Y.Oak 18" dia. bears N.54°W., 242 lks.
- A Y.Oak 18" dia. bears S.83½°W., 134 lks.

Ben B. Irving - R.L. Irving; Paul Abeel; Epperly - For:  
J.T. Epperly, July, 1926 - C.S. File 37/105, M 28-29  
-----

I found at this corner a rotten stake at a fence corner &  
an original BT in good condition (which I did not chop open)  
now a 16" B.Oak N.78½°E., 61 lks. Also, a B.Oak down and  
rotting but with scribe marks in the stump still legible  
S.79¾°W., 132 lks. From this evidence I set a 3" x 42" Oak  
post , from which

- A 16" B.Oak bears N.78°30'E., 39.4 ft. (old BT)
- 24" B.Oak bears N.23°18'W., 210 ft. mkd. S31 T26SR7W BT
- 14" B.Oak bears S.80°30'E., 59 ft. mkd S18 T26S R6W.
- 8" Fir bears S.40°50'W., 52 ft. mkd. S24 T26S R6W

Milo Godfrey, Deputy co. Surveyor - Vernon R.Tracy; Jack  
Barnett - Aug. 1964 - C.S. File 52/87-96  
-----

Found - 20" D.Fir S.41°W., 52.0 ft. prev. opened, good  
scribing visible.  
27" B.Oak N.78½°E., 39.4 ft. shows fairly good scar  
25" B.Oak S.80½°E., 59.0 ft. shows very plain scar.  
32" B.Oak N.23¼°W., 210 ft. shows very good scar.  
All trees, above, alive & in good condition.

Set - Brass cap at cor. mkd. County Surveyor's Office 1964  
T26S S 12 | S 7

R7W S 13 | S 18 R6W

New BT - To replace tree 210.0 ft. from corner,  
6" D.Fir N.15°W., 17.0 ft. mkd. S12 CS BT.

Corner is along NW side of old road or tail along foot of  
hill

Doug. Co. Surveyors Office - Randall Smith; Stephen Flause  
April 10, 1990 - C.S. File 64/9-2  
-----

Found - 1964 DCSO 2½" BC on a 1P" O.D. I.P. protruding 4"  
above ground. BC/IP leans 0.4 ft. north of  
plumb.

14" now 31" dia. B.Oak with a fully healed blaze  
bears N.78½°E., 39.4 ft. (agrees w/rec) Orig.  
(No other original BTs found)

PRIMARY CORNER DESCRIPTION Cor Secs 12, 13; 7 & 18 T26-6

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

Found - 1964 DCSO 2½" BC on a 1P" O.D. I.P. protruding 4" above ground. BC/IP leans 0.4 ft. north of plumb.  
14" now 31" dia. B.Oak with a fully healed blaze bears N.78½°E., 39.4 ft. (agrees w/rec) Orig. (No other original BTs found)  
8" now 23" dia. 1½ ft. tall D.Fir stump with a fully healed lower blaze bears S.41°W. 52.6 ft. (Rec. S.41°W., 52.0 ft.)  
14" now 25" dia. B.Oak with a fully healed double blaze bears S.80½°E., 59.0 ft. (agrees w/rec)  
24" now 35" dia. 2½ ft. tall Oak stump with a fully healed lower blaze bears N.23¼°W., 21.0 ft.  
6" now 7" dia. 1½ ft. tall D.Fir stump with a fully healed lower blaze bears N.13¼°W., 17.0 ft. (Rec. N.15°W., 17.0 ft.)  
New BTs- 8" dia. D.Fir double blazed & scribed "T26S R7W S12 CS BT" bears N.75¼°W., 15.9 ft.  
11" dia. D.Fir double blazed & scribed "T26S R7W S13 CS BT" bears S.12½°W., 91.0 ft.  
Corner lies at the intersection of a North and West running fence lines.

Fd OK, Glenn Baughman, November, 1991, M 114-24  
Fd OK, D. Collier, Feb. 1996, 1996-0037  
FD Ok, D. Edwards, Mar. 1997, M 126-65