

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 26 & 27

Alias	Description
Alias	Description
Alias	Description
Alias	Description

GLO survey by William P. Heydon, Deputy Surveyor, under contract No. 656, dated May 21, 1896 - (DCSO records Vol. 11 Page(s) 4664)

Set a yew post, 3 ft. long, 4" sq., 24" in the ground for ¼ sec. cor. mkd ¼ S on W face, from which

A fir, 48" dia., bears N.60°E., 210 lks., mkd: ¼ S BT.

A fir, 48" dia., bears N.50°W., 295 lks., mkd: ¼ S BT.

GLO survey by William P. Heydon, Deputy Surveyor, under contract No. 656, dated May 21, 1896 - (DCSO records Vol. 11 Page(s) 4715)

Correction of surveys as ordered by the Commissioner of the GLO under date of March 18, 1898:

The ¼ sec. cor. as reported in orig. notes. I dig pit 18x18x2" 3 ft. N of post & erase markings on NW witness tree. The bearing & distance to the NE witness tree is as reported by the Examiner, to wit: N.2°30'E., 219 lks.

~~MARVIN C. RAMSEY - FOR: J.H. BAXTER & CO. - WIT: J. D KIRKLIN & JAMES GOODIN - JULY 6-29, 1960 - C.S. FILE 51/116~~

~~DETERMINED FROM THE ORIG. BT:-~~

~~D.FIR, DEAD SNAG 50" BEARS N.60°E., 210 LKS. WITH PARTIAL SCRIBE MKS. IN THE TOP BLAZE, THE BOTTOM BLAZE HAS BEEN REMARKED BT.~~

~~D.FIR 50" BEARS N.50°W., 295 LKS., DOWN & DECAYED.~~

~~SET AN IRON PIPE 3' LONG 1½" DIA., 28" IN THE GROUND, MKD. RS404, FROM WHICH NEW BTs:~~

~~16" D.FIR BEARS S.76½°E., 11 LKS., MKD: ¼ S26 RS404 BT.~~

~~24" D.FIR BEARS N.42½°W., 64 LKS., MKD: ¼ S27 RS404 BT.~~

Douglas Co. Surveyors Office - James W. Byron, Deputy - Milo Godfrey - Clete Putman - April 20, 1961 - C.S. File 52/79-2

Found - Orig. 48", now 60" Fir Snag N.2½°E., 144.5 ft., shows good scribing on old face. "¼S".

Now 60" Fir that checks close for Orig. N.W. BT, recorded by Hayden 1896.

Set - Brass Cap at Corner Mkd ¼ S26|S27 T26S R8W County Surveyors Office, 1961

New BTs- 14" R.Fir bears S.71°E., 6.8 ft. scribed ¼ S26 CS BT

10" R.Fir bears N.44¼°W. 14.0 ft scribed ¼ S27 CS BT

NOTE 1 - We find cor. & BTs recorded by Ramsey 1960 bears S.64½°W., 101.7'. We do not destroy this cor. We find 60" R.Fir that bears N.60°E., 138.6' and we find not old scribing near base "BT". cont.

TOWNSHIP 26 RANGE 08 POINT IDENTIFIER # 500240

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 26 & 27

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Also old face above with part of center cut out but no scribing or scribe marks as Ramsey states. The sect. cut out of old face was done years ago. We do not find the NW BT. There is a down & rotted Fir within a few feet of the 1896 NW. There is no evidence left to indicate that it was a BT. The NE BT used by Ramsey faces to South and not S.60°W.

Note 2- Ramsey's corner was destroyed by Ramsey May 1961
C.S. File 51/116-2A&B

Fd. Ok M. McDowell 8/1985 - M99-18